Submit 3 Copies To Appropriate District State of New Mexico	C(7) Form C-103
Office Energy, Minerals and Natural Resource	S Revised March 25, 1999
Distinct I 1625 N. French Dr., Hobbs, NM 88240 30 31 $-123$	WELL API NO
811 South First, Artesia, NM 882/20 A OIL CONSERVATION DIVISION	30-015-23890
District III $\sqrt{2}$ = coop 1220 South St. Francis Dr.	5. Indicate Type of Lease
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM RELEIVED 87505 OCD - ARTESIA	0. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILLION TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:	7. Lease Name or Unit Agreement Name:
Oil Well Gas Well Other Plug & Abandon	Sara AHA Com
2. Name of Operator Yates Petroleum Corporation	8. Well No.
3. Address of Operator	9. Pool name or Wildcat
105 South Fourth Street - Artesia, NM 88210	Dagger Draw Upper Penn, South
4. Well Location	
Unit Letter I : 1980 feet from the South line and	660 feet from the East line
Section 11 Township 20S Range 24E	NMPM Eddy County
10. Elevation (Show whether DR, RKB, RT, GR	
3608' GR	
11. Check Appropriate Box to Indicate Nature of Notic	
	JBSEQUENT REPORT OF: ORK ALTERING CASING
PULL OR ALTER CASING DIMULTIPLE CASING TEST COMPLETION CEMENT JOB	AND
OTHER: OTHER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, an	
of stanting and many and model. OFE DITE 1102 For Multiple Completions. At	ach wellbore diagram of proposed completion
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At	
or recompilation.	ing equipment Rigged up rod
or recompilation. 9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment.	Shut well in for night.
or recompilation. 9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment.	Shut well in for night. gged up floor and tubing equipment.
or recompilation. 9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment.	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on
or recompilation. 9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment.	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on r night.
or recompilation. 9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment.	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on r night. rt plugging out well. Squeezed ed to 7650'. WOC 4 hours. Pumped
<ul> <li>or recompilation.</li> <li>9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment.</li> <li>9-19-2002 - Nippled down wellhead and nippled up BOP. Ri Turned tubing - does not want to release. Pumped 140 bbl tubing - still does not want to release. Shut well in for 9-20-2001 - Worked on tubing. Received permission to stat 50 sacks Class C Neat cement into perforations. Displace down tubing - did not pressure up. Resqueezed with 50 sates for sates and for the sate of the sate of</li></ul>	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on r night. rt plugging out well. Squeezed ed to 7650'. WOC 4 hours. Pumped
<ul> <li>or recompilation.</li> <li>9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment.</li> <li>9-19-2002 - Nippled down wellhead and nippled up BOP. Ri Turned tubing - does not want to release. Pumped 140 bbl tubing - still does not want to release. Shut well in for 9-20-2001 - Worked on tubing. Received permission to stat 50 sacks Class C Neat cement into perforations. Displace down tubing - did not pressure up. Resqueezed with 50 sa Shut well in for night.</li> </ul>	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on r night. rt plugging out well. Squeezed ed to 7650'. WOC 4 hours. Pumped cks Class C Neat cement. WOC.
<ul> <li>or recompilation.</li> <li>9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment.</li> <li>9-19-2002 - Nippled down wellhead and nippled up BOP. Ri Turned tubing - does not want to release. Pumped 140 bbl tubing - still does not want to release. Shut well in for 9-20-2001 - Worked on tubing. Received permission to state 50 sacks Class C Neat cement into perforations. Displace down tubing - did not pressure up. Resqueezed with 50 sa Shut well in for night.</li> <li>9-21-23-2002 - Pumped down tubing - did not pressure up.</li> </ul>	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on or night. art plugging out well. Squeezed ed to 7650'. WOC 4 hours. Pumped cks Class C Neat cement. WOC. Respotted 50 sacks Class C Neat
<ul> <li>or recompilation.</li> <li>9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment.</li> <li>9-19-2002 - Nippled down wellhead and nippled up BOP. Ri Turned tubing - does not want to release. Pumped 140 bbl tubing - still does not want to release. Shut well in for 9-20-2001 - Worked on tubing. Received permission to sta 50 sacks Class C Neat cement into perforations. Displace down tubing - did not pressure up. Resqueezed with 50 sa Shut well in for night.</li> <li>9-21-23-2002 - Pumped down tubing - did not pressure up. cement into perforations. Displaced to 7650'. WOC 4 how the spotted 50 sacks Class C Neat cement. WOC. Shut well</li> </ul>	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on r night. rt plugging out well. Squeezed ed to 7650'. WOC 4 hours. Pumped cks Class C Neat cement. WOC. Respotted 50 sacks Class C Neat rs. Still did not pressure up. in for night.
<ul> <li>or recompilation.</li> <li>9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment.</li> <li>9-19-2002 - Nippled down wellhead and nippled up BOP. Ri Turned tubing - does not want to release. Pumped 140 bbl tubing - still does not want to release. Shut well in for 9-20-2001 - Worked on tubing. Received permission to sta 50 sacks Class C Neat cement into perforations. Displace down tubing - did not pressure up. Resqueezed with 50 sa Shut well in for night.</li> <li>9-21-23-2002 - Pumped down tubing - did not pressure up. cement into perforations. Displaced to 7650'. WOC 4 how Resported 50 sacks Class C Neat cement. WOC. Shut well</li> <li>\$\cup 9-24-2002 - Pumped down tubing - still did not pressure up</li> </ul>	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on r night. rt plugging out well. Squeezed ed to 7650'. WOC 4 hours. Pumped cks Class C Neat cement. WOC. Respotted 50 sacks Class C Neat rs. Still did not pressure up. in for night. p. Pumped 50 sacks Class C Neat
<ul> <li>or recompilation.</li> <li>9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment.</li> <li>9-19-2002 - Nippled down wellhead and nippled up BOP. Ri Turned tubing - does not want to release. Pumped 140 bbl tubing - still does not want to release. Shut well in for 9-20-2001 - Worked on tubing. Received permission to sta 50 sacks Class C Neat cement into perforations. Displace down tubing - did not pressure up. Resqueezed with 50 sa Shut well in for night.</li> <li>9-21-23-2002 - Pumped down tubing - did not pressure up. cement into perforations. Displaced to 7650'. WOC 4 hour Resported 50 sacks Class C Neat cement. WOC. Shut well</li> <li>9-24-2002 - Pumped down tubing - still did not pressure up cement. Displaced to 7650'. WOC 4 hours. Still did not</li> </ul>	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on r night. rt plugging out well. Squeezed ed to 7650'. WOC 4 hours. Pumped cks Class C Neat cement. WOC. Respotted 50 sacks Class C Neat rs. Still did not pressure up. in for night. p. Pumped 50 sacks Class C Neat
<ul> <li>or recompilation.</li> <li>9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment.</li> <li>9-19-2002 - Nippled down wellhead and nippled up BOP. Ri Turned tubing - does not want to release. Pumped 140 bbl tubing - still does not want to release. Shut well in for 9-20-2001 - Worked on tubing. Received permission to sta 50 sacks Class C Neat cement into perforations. Displace down tubing - did not pressure up. Resqueezed with 50 sa Shut well in for night.</li> <li>9-21-23-2002 - Pumped down tubing - did not pressure up. cement into perforations. Displaced to 7650'. WOC 4 how Resported 50 sacks Class C Neat cement. WOC. Shut well</li> <li>\$\cup 9-24-2002 - Pumped down tubing - still did not pressure up</li> </ul>	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on r night. rt plugging out well. Squeezed ed to 7650'. WOC 4 hours. Pumped cks Class C Neat cement. WOC. Respotted 50 sacks Class C Neat rs. Still did not pressure up. in for night. p. Pumped 50 sacks Class C Neat pressure up. Respotted 50 sacks
<ul> <li>or recompilation.</li> <li>9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment.</li> <li>9-19-2002 - Nippled down wellhead and nippled up BOP. Ri Turned tubing - does not want to release. Pumped 140 bbl tubing - still does not want to release. Shut well in for 9-20-2001 - Worked on tubing. Received permission to stat 50 sacks Class C Neat cement into perforations. Displace down tubing - did not pressure up. Resqueezed with 50 sa Shut well in for night.</li> <li>9-21-23-2002 - Pumped down tubing - did not pressure up. cement into perforations. Displaced to 7650'. WOC 4 hour Resported 50 sacks Class C Neat cement. WOC. Shut well</li> <li>9-24-2002 - Pumped down tubing - still did not pressure up cement. Displaced to 7650'. WOC 4 hours. Still did not Class C Neat cement. WOC. Shut well in for night.</li> <li>I hereby certify that the information above is the and complete to the best of my knowled and the information above is the and complete to the best of my knowled and the pressure is the and complete to the best of my knowled and the pressure is the and complete to the best of my knowled and the pressure is the and complete to the best of my knowled and the pressure is the and complete to the best of my knowled and the pressure is the and complete to the best of my knowled and the pressure is the and complete to the best of my knowled and the pressure is the and complete to the best of my knowled and the pressure is the and complete to the best of my knowled and the pressure is the pressure in the pressure in the pressure is the pressure in the pressure in the pressure is the pressure in the pressure in the pressure in the pressure in the pressure is the pressure in the pressure in the pressure is the pressure in the pressur</li></ul>	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on r night. rt plugging out well. Squeezed ed to 7650'. WOC 4 hours. Pumped cks Class C Neat cement. WOC. Respotted 50 sacks Class C Neat rs. Still did not pressure up. in for night. p. Pumped 50 sacks Class C Neat pressure up. Respotted 50 sacks
<pre>or recompilation. 9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment. 9-19-2002 - Nippled down wellhead and nippled up BOP. Ri Turned tubing - does not want to release. Pumped 140 bbl tubing - still does not want to release. Shut well in for 9-20-2001 - Worked on tubing. Received permission to sta 50 sacks Class C Neat cement into perforations. Displace down tubing - did not pressure up. Resqueezed with 50 sa Shut well in for night. 9-21-23-2002 - Pumped down tubing - did not pressure up. cement into perforations. Displaced to 7650'. WOC 4 hour Respotted 50 sacks Class C Neat cement. WOC. Shut well 9-24-2002 - Pumped down tubing - still did not pressure up cement. Displaced to 7650'. WOC 4 hours. Still did not Class C Neat cement. WOC. Shut well in for night. I hereby certify that the information above is two and complete to the best of my knowled SIGNATURE</pre>	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on r night. rt plugging out well. Squeezed ed to 7650'. WOC 4 hours. Pumped cks Class C Neat cement. WOC. Respotted 50 sacks Class C Neat rs. Still did not pressure up. in for night. p. Pumped 50 sacks Class C Neat pressure up. Respotted 50 sacks edge and belief. CONTINUED ON NEXT PAGE:
<pre>or recompilation. 9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment. 9-19-2002 - Nippled down wellhead and nippled up BOP. Ri Turned tubing - does not want to release. Pumped 140 bbl tubing - still does not want to release. Shut well in for 9-20-2001 - Worked on tubing. Received permission to sta 50 sacks Class C Neat cement into perforations. Displace down tubing - did not pressure up. Resqueezed with 50 sa Shut well in for night. 9-21-23-2002 - Pumped down tubing - did not pressure up. cement into perforations. Displaced to 7650'. WOC 4 hour Respotted 50 sacks Class C Neat cement. WOC. Shut well 9-24-2002 - Pumped down tubing - still did not pressure up cement. Displaced to 7650'. WOC 4 hours. Still did not Class C Neat cement. WOC. Shut well in for night. I hereby certify that the information above is twe and complete to the best of my knowled SIGNATURE</pre>	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on r night. rt plugging out well. Squeezed ed to 7650'. WOC 4 hours. Pumped tecks Class C Neat cement. WOC. Respotted 50 sacks Class C Neat rs. Still did not pressure up. in for night. p. Pumped 50 sacks Class C Neat pressure up. Respotted 50 sacks edge and belief. CONTINUED ON NEXT PAGE: RY TECHNICIAN DATE 10-27-02
<pre>or recompilation. 9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment. 9-19-2002 - Nippled down wellhead and nippled up BOP. Ri Turned tubing - does not want to release. Pumped 140 bbl tubing - still does not want to release. Shut well in for 9-20-2001 - Worked on tubing. Received permission to sta 50 sacks Class C Neat cement into perforations. Displace down tubing - did not pressure up. Resqueezed with 50 sa Shut well in for night. 9-21-23-2002 - Pumped down tubing - did not pressure up. cement into perforations. Displaced to 7650'. WOC 4 hour Respotted 50 sacks Class C Neat cement. WOC. Shut well 9-24-2002 - Pumped down tubing - still did not pressure up cement. Displaced to 7650'. WOC 4 hours. Still did not Class C Neat cement. WOC. Shut well in for night. Thereby certify that the information above is two and complete to the best of my knowled SIGNATURE</pre>	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on r night. rt plugging out well. Squeezed ed to 7650'. WOC 4 hours. Pumped teks Class C Neat cement. WOC. Respotted 50 sacks Class C Neat trs. Still did not pressure up. in for night. p. Pumped 50 sacks Class C Neat pressure up. Respotted 50 sacks edge and belief. CONTINUED ON NEXT PAGE: RY TECHNICIAN DATE 10-27-02 Telephone No.748-1471
<pre>or recompilation. 9-18-2002 - Moved in and rigged up pulling unit and plugg equipment. POOH with rods. Rigged down rod equipment. 9-19-2002 - Nippled down wellhead and nippled up BOP. Ri Turned tubing - does not want to release. Pumped 140 bbl tubing - still does not want to release. Shut well in for 9-20-2001 - Worked on tubing. Received permission to sta 50 sacks Class C Neat cement into perforations. Displace down tubing - did not pressure up. Resqueezed with 50 sa Shut well in for night. 9-21-23-2002 - Pumped down tubing - did not pressure up. cement into perforations. Displaced to 7650'. WOC 4 hour Respotted 50 sacks Class C Neat cement. WOC. Shut well 9-24-2002 - Pumped down tubing - still did not pressure up cement. Displaced to 7650'. WOC 4 hours. Still did not Class C Neat cement. WOC. Shut well in for night. I hereby certify that the information above is two and complete to the best of my knowled SIGNATURE</pre>	Shut well in for night. gged up floor and tubing equipment. s water down well. Worked on r night. rt plugging out well. Squeezed ed to 7650'. WOC 4 hours. Pumped tecks Class C Neat cement. WOC. Respotted 50 sacks Class C Neat rs. Still did not pressure up. in for night. p. Pumped 50 sacks Class C Neat pressure up. Respotted 50 sacks edge and belief. CONTINUED ON NEXT PAGE: RY TECHNICIAN DATE 10-27-02