

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Encl. Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-23920
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-8096

7. Lease Name or Unit Agreement Name Conoco 7 State
8. Well No. 5
9. Pool name or Wildcat Millman, QN-GR, East

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator SDX Resources, Inc.
3. Address of Operator P. O. Box 5061, Midland, TX 79704	4. Well Location Unit Letter <u>F</u> : <u>2180</u> Feet From The <u>North</u> Line and <u>1740</u> Feet From The <u>West</u> Line Section <u>7</u> Township <u>19S</u> Range <u>29E</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3377.1	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Add additional perfs in Queen ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was spudded 2/2/82. 8-5/8" 24# casing set @ 372', cmted w/800 sxs cmt. Circ to surf. 4-1/2" J-55 9.5# set @ 2571', cmted w/850 sxs & circulated. Perfs: 2038-50', squeezed w/500 sxs; 2140'-46', 55-58', 73-79', 2054-68' & frac'd w/14,000 gals & 30,000# 20/40 sd each zone.

Plans are to TOH w/rods & pump. NU BOP & TOH w/tbg. TIH & set RBP @ 2025'. Circulate hole clean w/2% KCl & test RBP, casing & BOP to 1000 psi & TOH. Perforate as follows: 1 spf (3-3/8" csg guns) 1977', 78', 79', 80', 81', 82', 83', 84', 85', 92', 93', 94', 2002', 03', and 2004' (total 15 holes).

Acidize perfs w/2000 gals of 15% Ferchek acid w/30 balls @ 3-4 bpm. Flow back acid & swab test zone. Will frac if necessary. Prep to start work 8/13/96.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Janice Courtney TITLE Regulatory Tech DATE 8/09/96
TYPE OR PRINT NAME Janice Courtney TELEPHONE NO. 915/685-1761

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY TIM W. GUM TITLE DISTRICT I SUPERVISOR DATE AUG 20 1996

CONDITIONS OF APPROVAL, IF ANY: