

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-23932

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-8096

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Mitchell Energy Corporation

3. Address of Operator

P. O. Box 4000, The Woodlands, TX 77387

7. Lease Name or Unit Agreement Name

Conoco "7" State

8. Well No.

9

9. Pool name or Wildcat

E. Millman (Queen-Greyburg)

4. Well Location

Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line

Section 7 Township 19S Range 29E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3382.2' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug and Abandon as per the following procedure:

* 15 SXs
POOH w/rods, pump, and 2 3/8" tbgs. RIH w/tbg and set 35' cmt plug in 4 1/2" csg above top perf (2076'). Tag plug. Spot 25 sx plug @ top of Queen (1782'). Spot 25 sx plug at base of salt (685'). Spot 25 sx plug @ 8 5/8" shoe (369') and tag. Spot 10 sx cmt plug @ surface. Weld on cap and erect permanent abandonment marker. Load hole with gelled brine between all plugs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

James Blount

TITLE Engineer

DATE 11/13/91

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

* AS noted above

APPROVED BY

TITLE

DATE 11-21-91

CONDITIONS OF APPROVAL, IF ANY:

Plugging