	C	F	н О	0	FIELD TRIP REPORT						
	λ S S	C I	U R	A R	Nama - Lõ	arry Brooks	Date 11/17/81	Miles 67	District ]]		
	S I F	L I	S	T E	Time of Depar	rture 10:00 a.m.	Time of Return	3:00 p.m.	_Car NOF4693		
	A TION	Т Ү		R H O U R S	In the space performed, 1	In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken. Signature Raw Brocks					
0	0	D	5	-	-	Top of cement by t Rig up Schlumberge	oleum Corp. Petco A temperature survey w er to perf @ 1920' a with cement from 192	as @ 1980' nd try to	·		
								•			
					<u>Milc</u> UIC RFA _Othe	67.	Per Diem UIC RFA Other0-	Hours UIC RFA Other	5		
						INSPECTION			OF SPECIFIC WELL		
(		Well Repai Water Misha	ED keep ing Test ir/Wo flow ap or Con	ing Cleanu rkov <b>er</b>	p rela injo tes R = Ins tion ' O = Oth Rec	CLASSIFICATION erground Injection Con sted to injection proj ulting from injection ection and production ts, turface injection pections relating to R er - Inspections not r lamation Fund	trol - Any inspection of ect, facility, or well o into any well. (SWD, 2n cells, water flows or pr equipment, plugging, etc icclamation Fund Activity related to injection or T forcement action taken i below the letter U, R or	or $D = Dri$ r $P = Pro$ dry $I = Inj$ easure $C = Con$ .) $C_{I}$ S = SWI U = Unc he $G = Ger$ F = Fac n the $Q = Orb$	eduction jection abined prod. inj. veration lerground Storage heral Operation cility or location ating		