NM OIL CONS. COMMISSION

Drawer DD

	•			Artesia, NM 8	BETO		
Form 9-331 (May 1963)		JNITED STATE		SUBMIT IN TRIPLICA' (Other instructions on		approved. et Bureau No. 42-R1424.	
_	DEPARTMENT OF THE INTERIOR			verse side)	5. LEASE DESIG	5. LEASE DESIGNATION AND SERIAL NO.	
C/SF GEOLOGICAL SURVEY						NM 057510	
		CES AND REP		_WELLS	5. IF INDIAN, A	ALLOTTEE OR TRIBE NAME	
(Do not use this f	orm for propos: Use "APPLICA	als to drill or to deepe TION FOR PERMIT—"	n or plug under	De Completed Labers of C	ন		
1.				TOTAL	7. UNIT AGREE	MENT NAME	
MELT X METT CYR	OTHER		$\mathcal{H}_{\mathcal{K}}$	NOV 1 0 1001			
2. NAME OF OPERATOR			تاك	10 1 1 6 1381 3	8. FARM OR LE	ASE NAME	
Gulf Oil Corp	oration	·····		OIL & GAS	Bate	Federal 😾	
3. ADDRESS OF OPERATOR	11-66-	ND4 000/0	U.S	GEOLOGICAL SUBVEY	9. WELL NO.		
P. O. Box 670 4. Location of Well (Re	, HODDS,	NM 88240	17(DWFII NEW NEWS	1 What Shu	POOL, OR WILDCAT	
See also space 17 belov At surface	v.)		*	Control MENSINATION) '-'	ugart	
			1		11. SEC., T., R.,	M., OR BLK, AND	
660' FNL & 660' FWL NOV 17 1981					SURVEY	OR AREA	
					Sec 11-	T19S-R31E	
14. PERMIT NO.		15. ELEVATIONS (Show		GR, etc.) C. C.	12. COUNTY OF	PARISH 13. STATE	
	*		3594' GL	ARTESIA, OFFICE	. Eddy	NM	
16.	Check Ap	propriate Box To I	ndicate Natu	re of Notice, Report, o	or Other Data		
N						QUENT REPORT OF:	
TEST WATER SHUT-OF		PULL OR ALTER CASING		WATER SHUT-OFF			
FRACTURE TREAT	-	TULTIPLE COMPLETE		FRACTURE TREATMENT		AIRING WELL ERING CASING	
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING		NDONMENT*	
REPAIR WELL		HANGE PLANS		(Other) Casing	<u></u>	X	
(Other)			ll	(Note: Report res Completion or Rec	sults of multiple com completion Report and	pletion on Well Log form.)	
17. DESCRIBE PROPOSED OR	COMPLETED OPE	RATIONS (Clearly state	all pertinent de	talls, and give pertinent da and measured and true vo	otas including octim-	. to	
(4232') set a poz + Gilsoni 10-24-81. Ci	t 4240', te + floc rculate 3	DV tool at 30 ele & 50 sack 0 sacks cemen	00 '. Cem s 50/50 p t a b ove D	n 107 joints 5½" ent 1st stage wi oz + flocele. P V tool to surfac 5½" casing. Dri	th 160 sacks Plug down at e; cannot pu	50/50 9:20 A.M., mp into	
18. I hereby certify that	the foregoing is	toue and correct					
	Valle 1	<u></u>	A ** ~ * * *	milling Comment		11 0 01	
SIGNED	ER A CH	T PMAN	ITLEATER D	rilling Superint	engent DATE _	11-9-81	
(This space for Feder	al or State offic	ce use)					
APPROVED BY	VAV 1 Q 4	704 T	ITLE		DATE _		
APPROVED BY	PROVAL PER	451					

*See Instructions on Reverse Side