STATE OF NEW MEXIC						
ENERGY AND MINERALS DEPA						
	<u> </u>	IL CONSERVA-	TION DIVISIO	Ċ		
DISTRIBUTION		Р. О, ВОХ	2088 0505			Form C-103 Revised 10-1-73
SANTA FE		SANTA FE, NEW	MEXICO 8750	IVED		Kevised 10-1-73
FILE					[5a, Indicate Type o	1 Leuso
U.S.G.S. /			JUN 9	1000		Fao X
LAND OFFICE			0011 9	1982		
OPERATOR /			• •		5, State CE & Gas	Lease No.
			<u> </u>			
IDO NOT USE THIS FORM F	UNDRY NOTICES	AND REPORTS ON Y	WELLS ARTESIA, C	DFFICE		
· · · · · · · · · · · · · · · · · · ·					- 1 X X X X X X X X X X X X X X X X X X	. X X X X X X X X X X X Nonie
) DTHER-					
Virme of Operator					", Faun or Lease Rame	
Yates Petroleum Corporation					Rio Penasco RT Com	
Address of Operator	4		· · · · · · · · · · · · · · · · · · ·		. Weli No.	
207 South 4th	St., Artesia,	NM 88210				1
Location of Well					Trout tech and solve	
Н	1980	North	660		Und. Wolf	camp
UNIT LETTER	,/II	T FROM THE	LINE AND	FLET FROM	mmmi	7777777777
Deet	Э	100	25	T.	AIIIIIIIII	
THE EAST LINE,	SECTION	TOWNSHIP 195	RANGE ZJ	<u>с</u>	AHHHHH	ANN
TTTTTTTTTTTTTTT	TITTTY.	Elovation (show whether D			TITTITITI	arrist the first
	///////////////////////////////////////				L. County	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	TITITIA	<u> </u>	{		Eddy	ΔΠΠΠΠ
Ch.	eck Appropriate	Box To Indicate Na	ture of Notice, I	Report or Gt	her Data	
	OF INTENTION T			•	T REPORT OF:	
CREDAM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK		ALTERS	G CASING
			COMMENCE DRILLING O	님		· · · · ·
IMPORARILY ABANDON				<u>}</u>	PLUG AN	U ABANDONMENT
-LIL OR ALTEN CASING		CHANGE PLANS	CASING TEST AND CEMI			<u> </u>
			OTHER			ll
OTHER	······					

2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pulled tubing and packer. Set CIBP at 8850' w/35' cement on top. Ran Vann-system & perforated 7835-50' (60 shots). Gas TSTM. Squeezed perforations 7835-50' w/75 sx to 3500 psi. Ran Vannsystem and perforated 7810-17' w/10 .50" holes. Squeezed perforations 7810-17' w/75 sacks Class "H" cement to 3500 psi. Drilled cement retainer and cement. Cleaned out well to 7929'. WIH and perforated 7837-49' w/24 .50" holes. Swabbed well dry. Set CIBP at 7700' w/35' cement on top. WIH and perforated 6863-6913' w/15 .50" holes. Acidized perforations 6863-6913' w/2500 gallons 15% MCA and 3% KCL and ball sealers. Stabilized well at 140 psi on 1/8" choke = 55 mcfpd. WIH and perforated 6651-6672' w/10 .45" holes. Set RBP below perfs and packer above perfs and tested. Acidized well w/2000 gallons NEA and N2 with ball sealers. Flowed well back. Stabilized well at 70 psi on 1/8" choke. WIH and perforated 6569-97' w/10 .50" holes. Treated perfs 6569-97' w/2000 gallons 15% NEA and N2 plus ball sealers. Squeezed perfs 6569-97' w/75 sacks Class "C" cement to 3500 psi. Drilled out cement across perfs 6569-97'. WIH and perforated 6072-6108' w/17 .45" holes. Ran RBP and packer. Acidized perforations 6072-6108' w/2000 gallons 15% NEA and N2 plus ball sealers. Well flowed back and stabilized at 570 psi on 1/2" choke = 3650 mcfpd. Packer set at 6035'; RBP set at 6154'.

s. Thereby certify that the information above is true and comple	te to the bost of my knowledge and belief.	DATE	6-8-82
MOVED BY A Aussit	SUPERVISOR, DISTRICT I	DATE	JUN 29 1982