

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NM OIL & GAS
ARTESIA, NM 88210

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

CA #RNM 012

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Yates Petroleum Corporation

FEB 22 '88

3. ADDRESS OF OPERATOR

105 South 4th St., Artesia, NM 88210

O. C. D.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

1980' FNL & 660' FEL

ARTESIA, OFFICE

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Rio Penasco RT Com

9. WELL NO.

1

10. FIELD AND WELLS

Under Wolfcamp

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit H, Sec. 3-T19S-R25E

14. PERMIT NO

API #30-015-23978

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3479' GR

12. COUNTY OR PARISH

Eddy

13. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Refer letter dated 1/21/88 from BLM

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Re: 3162.4

Yates Petroleum Corporation sold gas from this well from November, 1982, through June, 1985, to Transwestern Pipeline. The gas went sour. YPC is now waiting for TWP to change the gas contract so that the gas can be put into the sour gas gathering system. Due to drilling Dagger Draw wells and limitations of horsepower, compression and volumes, Transwestern and Yates Petroleum cannot handle the Rio Penasco RT Com #1 gas before June 1, 1988. At that time, Transwestern will have sufficient compression to put the well on line for sales.

RECEIVED
FEB 16 8 12 AM '88

18. I hereby certify that the foregoing is true and correct

SIGNED *Janita Doolittle*

TITLE Production Supervisor

DATE 2-12-88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

2-19-88

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side