

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN THE MANNER
(Other instructions on the
reverse side)Form approved
Budget Bureau No. 42-11424

LEASE DESIGNATION AND SERIAL NO.

NM-19441

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	MAR 04 1983	7. UNIT AGREEMENT NAME	-----
2. NAME OF OPERATOR MORRIS R. ANTWEIL ✓	O. C. D.	8. FARM OR LEASE NAME Gulf Federal	
3. ADDRESS OF OPERATOR P. O. Box 2010 Hobbs, New Mexico 88240	ARTESIA, OFFICE	9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT Wildcat	
		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec 31-T19S-R30E	
14. PERMIT NO. -----	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3323.1 GR	12. COUNTY OR PARISH Eddy	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged and abandoned well as follows:

- 1) Loaded hole with fresh water.
- 2) Spotted 15 sx plug @ 1618' - 1540'
- 3) Waited 3 hours.
- 4) Tagged plug top at 1546'.
- 5) Circulated hole with mud.
- 6) Spotted 25 sx plug @ 1546' - 1250'.
- 7) Spotted 25 sx plug @ 425' - 125'.
- 8) Spotted 15 sx surface plug and set marker.

Plugged and abandoned January 28, 1983.

4 1/2" casing left surface to 1660' TD

Will notify Roswell Oil & Gas office when surface restoration
operations complete and location ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

(Orig. Sgd.) PETER W. CHESTER
APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

MAR 1 1983

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

TITLE

TITLE

DATE

FEB 2 1983

See Instructions on Reverse Side

OIL & GAS
MINERALS DIVISION
ROSWELL, NEW MEXICO