## RECEIVE FEB 1 8 1898 State of New Mexico Submit 3 Copies to Appropriate Energy, Minerals and Natural Resources Department **Revised 1-1-89** District Office DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION WELL API NO. 310 Old Santa Fe Trail, Room 206 30-015-24091 DISTRICT II Santa Fe, New Mexico 87503 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE FEE DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. V = 391SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK-TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" RECEIVED Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: GAS WELL X Exxon State WELL OTHER 2. Name of Operator 2345 Santa Fe Exploration Company 3. Address of Operator 9. Pool name or Wildcat 201 W. 3rd, Rosewell, NM 88201 Cemetary (MOrrow) Well Location Unit Letter L : 1980 Feet From The South West Line and Feet From The Line Township 20 South Range Eddy 25 East Section **NMPM** County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,422 GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER: OTHER:\_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 2-05-98 Cut 2 3/8" tbq. @ 9238 Got Approval from OCD to set CIBP @ 9238 1) 2-05-98 2) Set 4 1/2" CIBP @ 9238 2-05-98 Circ. hole w/10# brine w/25# salt get per bbl spot 25 sx on top 3) CIBP Cut 41/2" csg @ 8292 2-06-98 4) 2-09-98 Spot 23 sx pluq @ 8340 2-10-98 TAG TOC @ 8131 5) 1-10-98 Circ. hole w/10# brine w/25# salt get per bbl 6) 1-10-98 7) Spot 35sx plug 6690-6590 Spot 35 sx 3700-3600 2-20-98 8) 2-10-98 9) Spot 45sx plug 1400 WOC TAG TOC @ 1285 2-11-9810Spot 35 sx plug 400-300 2-11-98 11) Spot 10 sx plug 30-surf 2-11-98 12) .Cut off WH & install dry hole marker

SIGNATURE \_ 151 ( owwww. BILLY TYPE OR PRINT NAME

(This space for State Use)

APPROVED BY -

CONDITIONS OF APPROVAL, IF ANY:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.