

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

NM OIL CONS COMMISSION  
Drawer DD

Artesia, NM 88210  
FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

5. Lease Designation and Serial No.

NM-12246

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Oakason NV Federal #3

9. API Well No.

30-015-24095

10. Field and Pool, or Exploratory Area

Undesignated

11. County or Parish, State

Eddy Co., NM

SUBMIT IN TRIPLICATE

AUG 01 '94

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

YATES PETROLEUM CORPORATION

(505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2030' FNL & 1650' FEL of Section 34-T19S-R24E (Unit G, SWNE)

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☒ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other \_\_\_\_\_  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to abandon depleted Atoka zone 8653-8674' and recompleat higher to the Dagger Draw Canyon dolomite 7636-7678' as follows:

1. Nipple down tree, nipple up and test BOP. Release packer at 8595'. POOH with tubing string and packer.
2. Set CIBP at 8600' and cap with 35' of cement to abandon Atoka perms. 8653-8674'.
3. Perforate Canyon Dolomite with 4" casing gun as follows: 7636-7640' (5 holes), 7659-7663' (5 holes) and 7674-7678' (5 holes) (Total 15 holes - 1 SPF).
4. RIH w/production packer and tubing. Set packer at 7600'.
5. Acidize perforations 7636-7678' with 10000 gallons 20% NEFE HCL acid and ball sealers.
6. Swab well in and test.

14. I hereby certify that the foregoing is true and correct

Signed Rusty Klen

Title Production Clerk

Date July 21, 1994

(This space for Federal Official Signature) **(ORIG. SGD.) JOE G. LARA**

Approved by \_\_\_\_\_  
Conditions of approval, if any:

Title PETROLEUM ENGINEER

Date 7/28/94

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side