Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

DISTRICT I

## OIL CONSERVATION DIRECTOR

Revised 1-1-89

\_ DATE \_

P.O. Box 1980, Hobbs, NM 88240	P.O. Box 208		WELL API NO.		
DISTRICT II	Santa Fe, New Mexics [87504821992		30-015-24141		
P.O. Drawer DD, Artesia, NM 88210	Samuel 10, 110 W Moxiegy	u/ 50-₩200#=	5. Indicate Type of La	ase	
DISTRICT III O. C. D.		Q. C. D.			EE X
1000 Rio Brazos Rd., Aztec, NM 87410	A.4	PRESENTED THE PROPERTY OF THE	6. State Oil & Gas Le	ase No.	
SUNDRY NOT	ICES AND REPORTS ON WEL	LS			77777
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name		
DIFFERENT RESER	RVOIR. USE "APPLICATION FOR PEI -101) FOR SUCH PROPOSALS.)	RMIT"		T. B. WILLIAM	
1. Type of Well:					
well other Dry Hole			Genecco Com 14D		
2. Name of Operator  Meanburg Producing Co	mnany		8. Well No.		
Nearburg Producing Company 3. Address of Operator			9. Pool name or Wildcat		
P. O. Box 823085, Dailas, Texas 75382-3085			Cemetary Morrow		
4. Well Location	143, 16443 70002 0003		Cemetary M	JIT UW	
Unit LetterD : 660	Feet From The North	Line and 66	60 Feet From Th	eWest	Line
Section 14	Township 20S Ra	<sub>nge</sub> 25E		Eddy c	
	Township ZUS Ra  10. Elevation (Show whether		NMPM		County
	3,415.9' GR	, , , , , , , , , , , , ,			
11. Check	Appropriate Box to Indicate I	Nature of Notice, R	eport, or Other D	ata	
NOTICE OF INT			SEQUENT REF		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK			
				TERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING		GOPNS. L PLI	UG AND ABANDONM	ENT L	
PULL OR ALTER CASING			EMENT JOB		
OTHER:		OTHER:		<del></del>	🗆
<ol> <li>Describe Proposed or Completed Operat work) SEE RULE 1103.</li> </ol>	ions (Clearly state all pertinent details, an	d give pertinent dates, inclu	ding estimated date of sta	rting any proposed	<u> </u>
7/27/92 Mix and nump 2	25 sx Class H cement nl	ua from 9 500'	- 0 122'		
7/27/92 Mix and pump 25 sx Class H cement plug from 9,500' - 9,122'. 7/28/92 Tag cement plug at 9,103'. Mix, pump, and lay 25 sx cement plug from 8,800' -					
8,422'. 7/29/92 Pump 12 sx ce	ement plug from 7,610'	- 7 460' Set	retainer at 6	5 905 1 Dump	30
sx Class H cen	ment plug, left 70' cem	ent on top of r	etainer.	7,005 . rump	30
7/30/92 Set 200 sx cer	ment plug from 2,840'-	2,100' per Mik	e Williams (NA	10CD District	II
Office).	lug at 2 450' Spot 20	. av coment blu	a from 1 405!	1 2051	1100
2 hours and ta	lug at 2,450'. Spot 30 ag at 1,350'. Set an	sx cement pro	y from 1,425	- 1,325 . I	NUC So+
30 sx cement	plug from 950' - 850'	Set 30 sx c	ement blug fro	a = 1,350.	3E t 2 '
Set 10 sx ceme	ent surface plug. Set	dry hole marker		•	
		•		Post ID-	
				10-2-9 PXA	2
I hereby certify that the information above is true	and complete to the best of my knowledge and	belief.			
SIGNATURE Mildred	Inipkins m	B Production An	alyst	DATE 9/4/92	
TYPEORPRINTNAME Mildred Sin	npkins			TELEPHONE NO. 214/73	9-1778
(This space for State Use)					

— TITLE —

APPROVED BY-