

5. Cut off 2 7/8" tbg at 5800'. TOH with tbg. Pulled on 4½" and found parted. Recovered 1574' of 4½" casing.
6. WIH with overshot on 4½" casing and tied casing back together.
7. WIH with pker on 2 3/8" tbg and set at 5328' KB. Pressured to 2000#. Held. WIH with perf gun thru tbg and shot 4 holes in 4½" casing at 5737'. Cement squeeze with 84 sx Class H with 2% CaCl from 5737' up to 5500'. WOC. Tagged top of plug at 5726'. Not enough plug.
8. Spotted 12 sx Class H with 2% CaCl from 5721' up to 5559'. TOH. This plug covers Wolfcamp top.
9. Perforated 4 holes in casing at 2488'. WIH with pker and set at 2200'. Spotted 66 sx Class H with 2% CaCl in and out of 4½" casing from 2488' up to 2300'. WOC. Tagged top of plug 2321'. TOH. This plug covers Glorieta top.
10. Unset overshot on 4½" casing and TOH with 1574' of casing.
11. WIH with 2 3/8" tbg open ended and spotted 200 sx Class H with 2% CaCl from 1626' up to 1150'. WOC. Tagged top of plug at 1232'. This plug covers 4½" stub and 8 5/8" casing shoe.
12. Pulled up and spotted 30 sx Class H from 511' up to 410'. This plug covers 13 3/8" casing shoe.
13. Pulled up and spotted 50' surface plug 02-08-94. RDPU.
14. Cleaned location and set P&A marker. Will do surface restoration as per agreement with land owner (Ralph Schafer).

Note: Salt gel mud is between all plugs and Johnny Robinson, with NMOCD, witnessed plugging of well.