

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 South First, Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
 2040 South Pacheco
 Santa Fe, NM 87505

Form C-103
 Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-24192
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FRE ☐
2. Name of Operator Harvard Petroleum Corporation		6. State Oil & Gas Lease No. L-4053
3. Address of Operator PO Box 936, Roswell, NM, 88202-0936		7. Lease Name or Unit Agreement Name: Roy
4. Well Location Unit Letter <u>H</u> : 1980 feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line Section <u>23</u> Township <u>19 South</u> Range <u>27 East</u> NMPM Eddy County		8. Well No. 1
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3452' GR		9. Pool name or Wildcat Millman - Yates, Seven Rivers, Queen

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: Casing Integrity Test ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐


COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1/11/01 - MIRU PU, PU 2 3/8" tbg and packer, RIH to $\pm$ 1350' and set packer. (Perfs 1425-1897)
 Test backside to 500 psi for 30" with a chart recorder. Bleed off pressure, release pkr, TOH, RD PU and clean up location.



Notific N.M.O.C.D. to witness M.I.T.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Vice President DATE 1/9/01

Type or print name Jeff Harvard Telephone No. 505-623-1581
 (This space for State use)

APPROVED BY [Signature] TITLE Field Rep. II DATE 1/10/2001
 Conditions of approval, if any: