	1.
Submit 3 Copies To Appropriate District State of New Mexic	Form C-103
Office State of Ive V Ivie Av	411
District I Energy, Minerals and Natural 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District First Addis NM 88210 OIL CONSERVATION D	20.015.24102
811 South First, Artesia, Nivi 88210	5 Indicate Type of Lease
District III 2040 South Pachec 1000 Rio Brazos Rd., Aztec, NM 87410	I STATE AND FEEL II I
District IV Santa Fe, NIVI 8/30	0. State Off & Gas Lease No.
2040 South Pacheco, Santa Fe, NM 87505	L-4053
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR S	
PROPOSALS.)	Roy
1. Type of Well:	
Oil Well Gas Well Other	8. Well No.
2. Name of Operator Harvard Petroleum Corporation	8. Well No.
3. Address of Operator	9. Pool name or Wildcat
PO Box 936, Roswell, NM, 88202-0936	Millman - Yates, Seven Rivers, Queen
4. Well Location	
- XV iv X vv VV 1000 C v C vv dv Novel 1000 C	
Unit Letter H : 1980 feet from the North	line and _660feet from the _Eastline
Section 23 Township 19 South	Range 27 East NMPM Eddy County
10. Elevation (Show whether DR, I	
3452' GR	,,,
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON F	EMEDIAL WORK ALTERING CASING
	COMMENCE DRIVING ORNO
TEMPORARILY ABANDON	OMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	ASING TEST AND
COMPLETION	EMENT JOB
OTHER: Casing Integrity Test	OTHER:
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompilation.	
$1/11/01 - MIRU PU$, PU 2 3/8" tbg and packer, RIH to ± 1350 ' and set packer. (Perfs 1425-1897)	
Test backside to 500 psi for 30" with a chart recorder. Bleed off pressure, release pkr, TOH, RD	
PU and clean up location.	
	(0.10117)
. /	(40°) A (4)
√ 0	
$\mathcal{A} = \mathcal{A} \cup $	/o [*]
\sim $i + i + i$	(2) (200)
	「 RECEIVED
XM John Chan	「 RECEIVED
The to the	
	RECEIVED OCD - ARTESIA
Thereby certify that the information above is true and compare to the best	RECEIVED OCD - ARTESIA
I hereby certify that the information above is true and complete to the bes	t of my knowledge and belief.
I hereby certify that the information above is true and complete to the bes	RECEIVED OCD - ARTESIA
I hereby certify that the information above is true and complete to the best SIGNATURE TITLE	RECEIVED OCD - ARTESIA OF my knowledge and belief. Vice President DATE 1/9/01
I hereby certify that the information above is true and compare to the best SIGNATURE TITLE Type or print name Jeff Harvard	t of my knowledge and belief.
I hereby certify that the information above is true and compare to the best SIGNATURE Type or print name Jeff Harvard (This space for State use)	A of my knowledge and belief. Compared to the president
I hereby certify that the information above is true and compare to the best SIGNATURE TITLE Type or print name Jeff Harvard	A of my knowledge and belief. Compared to the president