

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

+ cl SF
Op

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

JAN 22 1990

WELL API NO.

30-015-24334

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Douglas

8. Well No.

1

9. Pool name or Wildcat

McMillan Upper Penn Gas

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Robert N. Enfield

3. Address of Operator

P. O. Box 2431, Santa Fe, NM 87501

4. Well Location

Unit Letter J : 1700 Feet From The South Line and 1650' Feet From The East Line

Section 7 Township 19S Range 27E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3270.8 GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) Move in and rig up. Pull tubing. Run 5½" CIBP to 7450' & set.
- (2) Spot 40 sk. cement plug from 7450' @ top of CIBP to 7100'.
- (3) Cut 5½" casing @ 5512'. & lay down.
- (4) Spot 40 sk. cement plug @ 5½" stub @ 5600'. WOC. Tag @ 5388'.
- (5) Spot 30 sk. cement plug @ 2675'.
- (6) Spot 50 sk. cement plug @ 2250'. WOC. Tag @ 2126'.
- (7) Spot 40 sk. cement plug @ 350'.
- (8) Spot 15 sk. cement plug @ surface & set up P & A marker.

Part ID-2
2-16-90
P & A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Raymond Maldonado

TITLE P & A Supervisor, BABER

DATE 1-19-90

TYPE OR PRINT NAME

Raymond Maldonado

TELEPHONE NO. 505-393-5516

(This space for State Use)

APPROVED BY

Johnny Robinson

TITLE OIL AND GAS INSPECTOR

DATE 3-23-90

CONDITIONS OF APPROVAL, IF ANY:

GW