

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN 1 LOCATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

3.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		RECEIVED	
2. NAME OF OPERATOR		JUL 15 1983	
3. ADDRESS OF OPERATOR		O. C. D.	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface		ARTESIA, OFFICE	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)	
		12. COUNTY OR PARISH 13. STATE	

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETS <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and spaces pertinent to this work.) *

4/11/83: Ran hydrostatic bailer, sand pump & drive bailer, recovered frac sand. Ran skirted magnet without recovery.

4/12/83: Killed well - unseated Otis Perma-Latch pkr. - Circ. hole w/2% KCL fresh wtr. containing additives. Pulled tbg. & pkr. - lost 2 rubbers off pkr. while coming out of hole.

4/13/83: Ran 1 3/4" x 1 1/4" cutrite shoe, joint of washpipe & tbg. to 11,976'. Broke circ. - started milling - made 6 1/2' - stopped making hole - ran impression block - had impression of pkr. spring. Attempted to mill again without success. Reran impression block - had impression of a pkr. spring. Recovery for the day: springs, junk, cuttings, rubber & frac sand.

4/14/83: Broke circ. - couldn't make any progress. POH, wash shoe was worn out. Ran impression block - no picture. Ran 2 prong wireline grapple without recovery. Ran drive bailer without recovery. Ran 2 prong grab without recovery. Ran alligator grab without recovery. Ran a new 1 3/4" x 1 1/4" x 15' cutrite shoe, 1 3/4" x 1 1/2" wash pipe & 130 stds. tbg. & shut down.

4/15/83: Tagged up @ 11,981'. Broke circ. - milled - recovered lots of rubber, 2 pieces of pkr. spring, frac sand, small pieces of slips and made 7' - quit making any hole - pulled

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE _____ DATE _____

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side