

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N.M. Oil Cons. Division
811 S. 1st Street
Artesia, NM 88210-2834

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Nearburg Producing Company

3. Address and Telephone No.
3300 N A St., Bldg 2, Suite 120, Midland, TX 79705

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
735' FSL and 660' FWL, Sec 35, T19S, R25E

5. Lease Designation and Serial No.
NMNM91079

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Gulf Federal Com #1-Y

9. API Well No.
30-015-24354

10. Field and Pool, or Exploratory Area
Cemetery Atoka, North

11. County or Parish, State

Eddy Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Set CIBP @ 8750'. Dump 35' cmt on plug.
2. Cut 4-1/2" csg @ 6500' pull (TOC by TS 6800').
3. Spot 35 sx plug 50' in and 50' out of 4-1/2" csg stub.
4. WOC. Tag stub plug.
5. Set 35 sx plug from 4120' to 4000' (Top Bone Spring 4060').
6. Set 35 sx plug from 2880' to 2730' (Base 8-5/8" @ 2820').
7. Set 35 sx plug from 405' to 300' (Base 13-3/8" @ 355').
8. Set surface plug from 30' to surface.
9. Set dry hole marker.

RECEIVED
OCD - ARTESIA

14. I hereby certify that the foregoing is true and correct

Signed Gary Gourley
(This space for Federal or State office use)

Title Production Analyst

Date 07/26/00

Approved by (ORIG. SGD) GARY GOURLEY
Conditions of approval, if any:

Title PETROLEUM ENGINEER

Date AUG 18 2000

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side