

NEW MEXICO "0" STATE COMM #1/ /7/
04-02,03 CREWS OFF

NEW MEXICO "0" STATE COMM #1/ /7/
04-04 CREWS OFF/ 70 HRS SITP 1950 PSI

NEW MEXICO "0" STATE COMM #1/ /8/
04-05 BENNETT & CATHEY RUN BHP W/GRADIENT FROM 5000-10,871/SURF PRESS 1917, BHP 4873, BH TEMP 214, FL 5120, BLED WELL TO 0 PSI IN 3/4 HR W/NO FLUID REC/IN 3 HRS SWAB 0 BO 14 BLAW, FL 5200-10,700/ SI/SDFN -6 BLAW/T-348,415 I-546,780

NEW MEXICO "0" STATE COMM #1/ /9/
04-06 13 HRS SI, TP 1400#/BLED TO 0 IN 46 MIN/IN 1-1/2 HRS SWAB 0 BO 3 BLAW, FL 6500-SCATTERED/HOWCO FRAC PERFS 10,802-941 W/30,000 GALS ACID GEL IT W/10,000 GALS CO₂ & 20,000# 20-40 SD & 16,000# CARBOPROP/TAGGED W/TAGMASTER/BD 8050 MAX 9200 MIN 8050 AVG 8700 FINAL 9200 ISIP 4200 15 MIN SIP 3720 AIR 10.8 BPM, JC 1:37 PM -775 BLW/SI 1-1/2 HRS, TP 3720-3425, IN 15 HRS END 6 AM F 0 BO 330 BLW, 10/64 - 14/64 CHK, TP 3425-600/ STILL REC LOAD WTR & CO₂ THIS AM, GAS WILL NOT BURN / -445 BLW/T-348,415 I-599,976

NEW MEXICO "0" STATE COMM #1/ /10/
04-07 IN 4 HRS F 0 BO 7 BLW, 16/64 CHK, TP 600-550/ TURN THRU TESTER/IN 4-1/2 HRS F 0 BO 5 BLW, 32/64 CHK, TP 550-125/FARO 110 MCF AT END OF FLOW/OPEN TO FULL CHK, WELL BLED DOWN IMMEDIATELY/BEGAN SWAB 1ST RUN WENT TO PKR AT 10,728, REC 2 BLW/SHUT DOWN 1 HR/ 2ND SWAB RUN TO PKR, REC 1/2 BLW/SHUT DOWN 1-1/2 HRS/ 3RD SWAB RUN TO PKR, REC 1/2 BLO/NO SOLID FL/SI/SDFN -430 BLW/11 HRS SITP END 6 AM 1320/ T-348,415 I-548,400