

6. HOWCO ACDZ PERFS 9468-87 W/2400 GALS 15% NEHCL & 50 - 7/8" RCNBS EVENLY SPACED THRUOUT. PMP @ 4-5 BPM. MX TP 6000 PSI. FLUSH TO BTM PERF W/2% KCL WTR.
7. FLOW & SWAB BACK LOAD & ACID WTR. EVAL FLUID CONTENT & RATE. (PUT ON ARTIFICIAL LIFT IF NECESSARY.)
8. ID SET VI ECONOMICAL TO PRODUCE, OBTAIN POTENTIAL TEST OR 4 PT FLOW TEST IF GAS PRODUCTION SIGNIFICANT.
9. IF SET VI UNECONOMICAL TO PRODUCE, WILL SUBMIT PROCEDURE TO SQZ OFF PERFS, CLN OUT & CONTINUE PRODUCING FROM CISCO ZONE.