

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN CRIMINAL
(Other instructions on re-
verse 1985)
NEW MEXICO

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-2416000

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER

APR 29 '88

2. NAME OF OPERATOR

Conoco Inc. ✓

3. ADDRESS OF OPERATOR

P.O. Box 460 - Hobbs, New Mexico 88240

ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

810' FSL & 990' FWL - Unit Letter M

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Tuesday Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Wolfcamp

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

34-19S-29E

14. PERMIT NO.

30-015-25123

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3334' GL

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

Perf, Acidize & Test Lower Wolfcamp

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Pull dual string. Load long & short strings w/10 ppq pkr fluid (10# brine w/10 gals 100 lbs Conoco pkr fluid #1.) POOH w/ short string. Pick up 2 3/8" long string to release hydraulic set dual pkr set at 9270'. Pick up long string to release HB hydraulic set packer at 9750'. If long string doesn't hold hydrostatic spot 4 bbls Templog across upper Morrow perms. POOH. Remove Baker A-3 Lok Set pkr & isolate upper Morrow by setting 7" CIBP at 11,020'. Dump 8 sxs (35') of class H' cmt on top of CIBP w/ dump barrel. RIH w/ Baker A-3 Lok Set pkr. Pressure test CIBP to 500 psi for 1/2 hr w/10 ppq pkr fluid. Leak off must not exceed 10%. POOH w/ pkr. Isolate Cisco Perfs. Set 7" CIBP at 9770'. Dump 8 sxs class "H" cmt on top of CIBP. Circulate hole w/ 2% RCL TFW. Perforate Lower Wolfcamp at 9308' - 9329' w/ 4 jspt. POOH w/ cs9 gun. Kill well w/ flowing. RIH w/ pkr & set at 9745'. Test CIBP to 2000 psi for 15 mins. Release pkr & pickle Hg

18. I hereby certify that the foregoing is true and correct

SIGNED DF FINNEY

TITLE Administrative Supervisor

DATE March 28, 1988

(This space for general or State office use)

APPROVED BY Robert Adams

TITLE Supervisor

DATE 4-15-88

CONDITIONS OF APPROVAL, IF ANY:

*See instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) File