

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

APR 24 1993
O.C.D.
OFFICE

API NO. (assigned by OCD on New Wells)

30-015-25151

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

N/A

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL

GAS

WELL ☐

WELL ☐

OTHER

DRY HOLE, TA'D

2. Name of Operator

CHEVRON U.S.A. INC.

3. Address of Operator

P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE

8. Well No.

1

9. Pool name or Wildcat

DRY HOLE, NEVER PRODUCED

4. Well Location

Unit Letter

A

:

660

Feet From The NORTH

Line and

660

Feet From The

Section

36

Township

18S

Range

31E

NMPM

West

EAST

Line

TEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3659' GR

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

☐

PLUG AND ABANDON

☒

TEMPORARILY ABANDON

☐

CHANGE PLANS

☐

PULL OR ALTER CASING

☐

OTHER:

☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK

☐

ALTER CASING

☐

COMMENCE DRILLING OPNS.

☐

PLUG AND ABAN.

☐

CASING TEST AND CMT JOB

☐

OTHER:

☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work) SEE RULE 1103.

WE PROPOSE TO PLUG AND ABANDON THIS WELL AS FOLLOWS:

WELL DRILLED IN 1985 AS A DRY DEVELOPMENT WELL & TEMPORARILY ABANDONED.

11-3/4" SURFACE CASING SET @ 350', 8-5/8" CASING SET @ 2350 & 5-1/2" CASING SET @ 4010'.

CIBP WAS SET @ 3701 WITH 5 SX CMT ON TOP AND CIBP WAS SET @ 2700' WITH 5 SX CMT
ON TOP. WE PROPOSE TO PLACE 15 SACKS 2500-2700', 15 SACKS PLUG 2300-2480' TAG.

(COVERS 8-5/8 SHOE) 15 SX PLUG 2125-2225 (COVERS BOTTOM OF SALT). 15 SX PLUG 935-1035'.

(TOP OF SALT). 15 SACKS PLUG 300-400', (COVERS 11-3/4" SHOE) TAG.

AND A 50 SACK PLUG FROM 200' TO SURFACE (PERF @ 200' & SQZ F/SURFACE)

PULL DEAD MAN ANCHORS, FILL PITS, LEVEL LOCATION, PLACE P&A MARKER.

CHANGE STATUS OF WELL TO PLUGGED AND ABANDONED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Nita Rice

TITLE

TECHNICAL ASSISTANT

DATE:

3/22/93

TYPE OR PRINT NAME

NITA RICE

TELEPHONE NO. (915)687-7436

APPROVED BY

[Signature]

TITLE

[Signature]

DATE

3/30/93

CONDITIONS OF APPROVAL, IF ANY: