Form 3160-5 (November 1983) Formerly 9-331)	UNITED STAT DEPARTM 'T OF THE BUREAU OF LAND MAN	INTERIORISCORTES	5. LEASE DESIGNATION AND SERIAL NO 471 <u>LC-029388 (d)</u>		
	NDRY NOTICES AND RE	PORTS ON WEELS pen or plus here to a dimension received. for shere proposeds) By	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
OIL GAS WELL WELL	OTHER	OCT 3 1 1985	7. UNIT AGREEMENT NAME		
2. NAME OF OPERATOR			8. FARM OR LEASE NAME		
Marathon O 3. ADDRESS OF OPERAT	il Company		Johnson "B" Fed.		
P. O. Box	2409 Hobbs, NM 88240	and an end of the second s	3		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements." See also space 17 below.) At surface 660' FNL & 1980' FWL			10. FIELD AND POOL, OR WILDCAT		
			Undesignated (Bone Spring		
	000 111 4 1900	1 411	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA		
			Sec. 11, T18S, R31E		
14. PERMIT NO.	4. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR. etc.)		12. COUNTY OR PARISH 13. STATE		
Not available GL 3753', KB 3764.20'			EddyNM		
16.	Check Appropriate Box To	Indicate Nature of Notice, Report, or C	Other Data		
NOTICE OF INTENTION TO :		S. BSEQ	SUBSEQUENT REPORT OF :		
TEST WATER SHUT-	OFF PULL OR ALTER CASING	WATER SHUT-OFF	BEPAIRING WELL		
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTEBING CASING		
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*		
REPAIR WELL	CHANGE PLANS	(OCINET)			
(Other)		(NOTE : Report results Completion or Recomp	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		
17. DESCRIBE PROPOSED (OR COMPLETED OPERATIONS (Clearly state	all pertinent details, and give pertinent dates, osurface locations and measured and true vertic	, including estimated date of starting any		
nent to this work.		source countries and measured and five vertice	ar acheno tot un maiscis and fonce belli-		
-					

Spudded 17 1/2" hole at 1:00 p.m. on 10-15-85. Drilled to 600'. Ran 15 joints of 13 3/8", 48#/ft., H-40, ST&C to 598' and cemented with 700 sacks; circulated 250 sacks to pit. Nippled up and tested blowout preventers to 1000 psi. Drilled out 13 3/8" casing shoe and drilled 11" hole to 2700'. Ran 65 joints of 8 5/8", 24 and 32#/ft., K-55 to 2700'. Cemented with 1300 sacks of Lite followed with 250 sacks of Class "C", circulated 405 sacks to pit. Nippled up and tested blowout preventers and casing to 3000 psi. Drilled out shoe and drilling ahead with 7 7/8" bit.

18. I hereby centify that the foregoing is true and correct SIGNED Steven A. Pohler	TITLE Production Engineer		
(This space for Federal or State office use)			
CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE	
OCT 30 1985 +s	ee Instructions on Reverse Side		

CARLSBARS. C. Section 1001 COakes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.