

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN THE MANNER
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.
LEASE DESIGNATION AND SERIAL NO.
NM-14206

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR Ralph Nix Oil, Inc.		7. UNIT AGREEMENT NAME
3. ADDRESS OF OPERATOR P. O. Box 440, Artesia, New Mexico 88210		8. FARM OR LEASE NAME B & B Federal
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 1980' FWL, Sec. 12, T-19-S, R-26-E, ARTESIA OFFICE		9. WELL NO. 1
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT Wildcat - Grayburg
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3307.5 GL		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 12, T-19-S, R-26-E
		12. COUNTY OR PARISH Eddy
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☒(Other) Perforate ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3/2/87 Set cast iron bridge plug at 1798' KB. Set 35' cement on top of bridge plug. GIH w/Hyperjet II 4" csng gun .48 cal. Shot 4 spf (90 deg. phase) 1266' to 1280' KB total 57 shots. Ran tbg. w/seating nipple to 1307' GL.

3/3/87 Acidized w/2500 gal. 15% NEFE acid plus additives. Formation broke 1820 psi, max psi 1830, avg. psi 1300, max rate 4.6 bpm, avg. rate 4.3 bpm. Total acid 60 bbls, total diesel 34.3 bbls. Total load 94.3 bbls.

3/4/87 Ran rods and started pumpjack at 10:30 am. Testing well for potential.

ACCEPTED FOR RECORD

MAR 10 1987

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE President

DATE 3/6/87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: