

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to complete a well back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR
Robert N. Enfield
3. ADDRESS OF OPERATOR
P.O. Box 2431, Santa Fe, NM 87504-2431
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
1835' FNL & 2310' FWL of Sec. 5
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input checked="" type="checkbox"/>
(other) <input type="checkbox"/>	<input type="checkbox"/>

5. LEASE
NM-45227
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Chevron Federal Comm.
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Undesignated Penn
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 5, T19S, R27E
12. COUNTY OR PARISH
Eddy
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3280 GI

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugging Operations began 9/17/86

Set CIBP at 7900'-spot 15 sx plug from 7900-7697'

spot 15 sx plug from 7225'-7022'

Go in hole & shoot off 4-1/2" casing at approx. 6342'

Displace hole with 10# brine

Spot 60 sx plug from 6387' - 6083', Tagged plug at 6100'

Spot 40 sx plug from 5000' - 4860'

Spot 40 sx plug from 3975' - 3835'

Spot 75 sx plug at 2458', Tagged plug at 2255'

Spot 40 sx plug from 1650' - 1550'

Spot 40 sx plug from 1350' - 1250'

Spot 75 sx plug at 350', Top Plug tagged at 80'

Cut off 13-3/8" & 8-5/8" starting head

Spot 10 sx plug at surface. Welded on top plate & installed dryhole marker.

Job complete 9/22/86. All plugs that were tagged were witnessed by BLM representative.

I hereby certify that the foregoing is true and correct

SIGNED Robert N. Enfield TITLE Operator DATE 10/7/86

(This space for Federal or State office use)

APPROVED BY 10-27-86 TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

Post FD-2
10-17-86
AAA