

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(One set of instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

215F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Harvey E. Yates Company

JAN 19 '88

3. ADDRESS OF OPERATOR

P.O. Box 1933, Roswell, New Mexico 88202

O. C. D.

ARTESIA OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

1980' FNL & 660' FEL

1930'

14. PERMIT NO.

API #30-015-25740

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3766' KB

3755' GL

5. LEASE DESIGNATION AND SERIAL NO

LC 062052

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hudson 11 Federal

9. WELL NO.

#2

10. FIELD AND POOL, OR WILDCAT

Tamano Eone Spring

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 11, T18S, R31E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANT

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 9-22-87 Perforate 8115-51 (OA) acidize w/2000 glas 20% HCl
9-29-87 Acidize w/5000 gal 20% HCL, 3000# rock salt & 7500 gals over flush; (8115-51')
9-30-87 Hang back on pump & test
12-8-87 Squeeze perfs 7934- 8151' w/retainer @ 7886'. Squeeze w/281 sxs Cl "A" to 3000#.
12-10-87 Drill out from 7886' to 8151' & clean out to 8771'. Circ hole clean.
12-12-87 Perf 1 JS @ 8695-8424 (11 holes). Acidize w/300 gals 7 1/2% NEFE, followed w/1000 gals same.
12-17-87 Acidize w/4000 gals 7 1/2% MSR 150 (8424-8695 perfs (OA))
12-19-87 Frac perfs (8424-8695' (OA)) w/90,000 gals WF 70 & 60 w/159,000# 16-30 sd & 40,000# 16-30 resin coated sand.
12-23-87 Run SN to 8150 w/anchor @ 7825. Ran pump & rods & hang on production. Turn over to pumper.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Manager/Engineer

DATE 12-30-87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

SJS