STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

N. D. WRECEIVED

ENERGY AND MINEHALS DEPARTIMENT	OIL CONSERVAT	TION DIVÎSÎÔN	Form C-103 .
no. or Corice Statistic	Р. О. ВОХ	2088	Revised 10-1-79
DISTRIBUTION	SANTA FE, NEW	мехісо ⁸⁷⁶⁰¹ 24 '88	
SANTA FK	,	UCI. 24 00	Sa. Indicate Type of Lease
FILE			State Fee X
U.S.O.S.	_	O. C. D.	5. State Otl & Gas Lease No.
LAND OFFICE		ARTESIA, OFFICE	
OPERATOR V		7	TITITITITITI TO
	HOTICES AND DEPORTS ON	WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPLE OR PLUG BACK TO A DIFFERENT RESERVOIR.			
(DO HOT USE THIS FURN OOD	YOR PERMIT -" (FORM C-101) FOR SUC.		7. Unit Agreement Name
1.			
OIL X GAB WILL OTHER-			8. Farm or Lease Hame
2. Name of Operator			Decor 7W
Yates Petroleum Corporation			Dagger ZW
rates retroiedin cor	Pozas		9. Watt 140.
). Address of Operator	MM 98210		1
105 South 4th St.,	Artesia, NH 00210		10. Field and Pool, or Wildcat
		,	No. Dagger Draw Up Penn
v 198	30 FEET FROM THE South	LINE AND 1980 FEET FR	TITITITITI MO
	30 TOWNSHIP 198	RANGE 25E NM	
THE West LINE, SECTION	TOWNSHIP		777777777444444
	15. Elevation (Show whether	DF. RT. GR. etc.)	12. County
	3564'	CR	Eddy ()
			0.1 0.4
16. Check At	ppropriate Box To Indicate N	lature of Notice, Report or	Other Data
Check A	SUZION TO	SUBSEQUE	ENT REPORT OF:
NOTICE OF INT	ENTION TO:		
	С	REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	1	PLUG AND ABANDONMENT
[]		COMMENCE DRILLING OPHS.	
TEMPORARILY ABANDON	CHANGE PLANS	CASING TEST AND CEMENT JOB	ional holes, treat
PULL OR ALTER CASING		OTHER Perforate addit	Tonar noics, creas
	. [
OTHER			formaling and proposes
2 1 1 4 0 10	rations (Clearly state all pertinent de	ails, and give pertinent dates, inclu	ding estimated date of starting any propose
17. Describe Proposed or Completed Openivork) SEE RULE 1103.	titiona (este as)		
		f-11orro •	
Perforated additional	holes in producing zon	e as 10110ws.	1 33 35 37, 49, 51,
Parforated 7685-7753	" w/10 .42" holes as f	ollows: /685, 90, //3.	1, 55, 55, 57, 12, 52,
Periorated 7005 77552	ted with (1) 1000 gals	15% NEFE acid w/inhibit	tor, then 50# Bloc;
52 and //53½ . Irea	tel with (1) 1000 gaze	O# Bloc and 10 ball sea	alers.; (3) 2500 gals
(2) 1500 gals of acid	ted with (1) 1000 gars with inhibitor, then 5 and 10 ball sealers; (4)	2500 gale acid and 63	bbls flush.
acid, then 75# Bloc a	nd 10 ball sealers; (4)	3000 gais acid and 03	
Returned well to prod	luction.		
Returned well to prod			
Work done 10-20-88.			
	•		
		and my knowledge and belief.	
18. I hereby certify that the information	above is true and complete to the bea	t of the stinmings are persent	
γ			10.01.00
) ·	115	Production Supervisor	DATE 10-21-88
* ICHTO / 1 / Clarely	1/C(())		
//	Original Signed By		OCT 2 4 1988
V	Mike Williams TITLE		DATE OUT NO 2

Mike Williams