

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	☒
LAND OFFICE	
OPERATOR	☒

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

NOV 25 '88

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease

State ☒ Fee ☐

5. State Oil & Gas Lease No.

NM-4681

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator ARCO OIL AND GAS COMPANY	8. Farm or Lease Name STATE 2
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240	9. Well No. 2
4. Location of Well UNIT LETTER C, 400 FEET FROM THE North LINE AND 2250 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 19S RANGE 30E NMPM.	10. Field and Pool, or Wildcat SHUGART YATES 7RQ GRBC
15. Elevation (Show whether DF, RT, GR, etc.) GR 3523.7	12. County EDDY

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1603.

11-10-88 - MIRU, POH w/CA, RIH w/W.S., RBP + PKR, set RBP @ 3090', set PAR @ 3058', Test to 1500# - Tested OK. POH w/PKR, dump sand on RBP. SION.

11-11-88 - Perf upper Queen w/ 1 JS @ 3023', 25', 27', 31', 35', 37', 39', 41', 45', 47', 49', 51' and 3053' RIH w/PKR + set @ 2931 - Test csg to 1000#. Acidize perfs 3023'-3053' w/1200 gal 15% NEFE. ISIP = 1000#.

11-12-88 - Swabbed 10 hrs - recovered 15 BO, 51 BW, SITP + 200#.

11-13-88 - MIRU B. J. Titan, Frac upper Queen perfs, 3023'-3053' - SDON.

11-14-88 - In 10 hrs swab 20 BO, 130 BW.

11-16-88 - Circulate out to RBP, POH w/RBP, RIH w/PKR and resume swab test.

11-17-88 - In 11 hrs swab 93 BO and 79 BW.

11-19-88 - RIH w/CA begin pumping.

11-22-88 - In 24 hrs pmpd 100 BO, 55 BW, 40 MCFG @ 10-64" SPM, CP 30.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Services Supervisor DATE 11-23-88

Original Signed By
Mike Williams

APPROVED BY _____ TITLE _____ DATE NOV 28 1988

CONDITIONS OF APPROVAL, IF ANY: