

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-015-25885

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.
013545

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
Anderson 11

1. Type of Well:

OIL	GAS	
WELL	WELL	X
		OTHER

2. Name of Operator
Nearburg Producing Company

8. Well No. 1

3. Address of Operator
P. O. Box 823085, Dallas, TX 75382-3085

9. Pool name or Wildcat

4. Well Location
Unit Letter E : 1980 Feet From The North Line and 330 Feet From The West Line
Section 11 Township 20S Range 25E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input checked="" type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		
OTHER:			<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: _____

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) MIRU plugging unit. Set CIBP @ 9350' w/5 sx cement.
- 2) Fill hole w/25#/bbl gel mud
- 3) Pump 25 sacks Premium Plus cement from ^{7800'}~~9050'~~ to ^{7700'}~~8672'~~
- 4) Pump 25 sacks Premium Plus cement from 5672' to 5294'.
- 5) PU csg and cut @ 2100' or free point and LD.
- 6) Pump 60 sx PP cement from 2300' to 1900'. (4-1/2" csg stub)
WOC f/3 hrs. RIH and tag TOC.
- 7) Pump 50 sacks Premium Plus cement from ^{1410'}~~1316'~~ to ^{1310'}~~1216'~~. TAG TOC.
- 8) Pump ²³⁰~~25~~ sacks Premium Plus cement from ^{420'}~~371'~~ to ^{320'}~~330'~~.
- 9) Surface plug w/10 sx PP cement. Set dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE H. R. Willis TITLE Drilling Supt. DATE 7/20/91
TYPE OR PRINT NAME H. R. Willis TELEPHONE NO. 397-4186

(This space for State Use)

APPROVED BY [Signature] TITLE Director DATE 1-11-77

CONDITIONS OF APPROVAL, IF ANY: