

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED
OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501
DEC 13 '88
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78
API #30-015-25896

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. LG 7123	
7. Unit Agreement Name	
8. Farm or Lease Name Kudu AFM State Com	
9. Well No. 1	
10. Field and Pool, or Wildcat Undes. San Andres	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Yates Petroleum Corporation	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Location of Well UNIT LETTER <u>J</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>10</u> TOWNSHIP <u>19S</u> RANGE <u>24E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 3673.5' GR	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <u>Plugback, perforate, treat</u> <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP 4900' w/35' cement on top. Cut 5-1/2" casing at 4110'. Circulated hole w/260 bbls brine gel. Laid down 97 joints 5-1/2" and 1 cutoff.
Spot plug #1 w/90 sx Class "C" Neat 4144-3800'.
Spot plug #2 w/35 sx Class "C" Neat 1905-1805'.
Spot plug #3 w/53 sx Class "C" w/2% 1327-1190'.

Perforated 1054-1180' w/12 .45" holes as follows 1054, 65, 75, 98, 1106, 14, 27, 35, 40, 48, 55, and 1180'. Acidized perfs 1054-1180' w/1500 gals 20% NEFE acid.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mike Williams TITLE Production Supervisor DATE 12-9-88

Original Signed By
Mike Williams

APPROVED BY _____ TITLE _____ DATE DEC 19 1988

CONDITIONS OF APPROVAL, IF ANY: