Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89 + F

to Appropriate District Office	Energy, Minerals and Natural Re	esources Department	Revised 1-1-89
DISTRICT I	OIL CONSERVATIO	N DIVISION	<u></u>
P.O. Box 1980, Hoods, NM 88240 P.O. Box 2088		WELL API NO. 30-015-25926	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	FEB 28 Sapta Fe, New Mexico 87504-2088		5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No. LG 1525
SUNDRY NO (DO NOT USE THIS FORM FOR F DIFFERENT RES	ARIESIA, OFFICE OTICES AND REPORTS ON WELPROPOSALS TO DRILL OR TO DEEPEN SERVOIR, USE "APPLICATION FOR PER 1 C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Weli: OIL OAS WELL X WELL	OTHER		State CO Com
2. Name of Operator YATES PETROLEUM CORPORATION			8. Well No.
3. Address of Operator		.	9. Pool name or Wildcat
105 South 4th St., A	rtesia, NM 88210	·	North Dagger Draw Upper Penn
4. Well Location			
Unit Letter \underline{D} : $\underline{660}$	Feet From The North	Line and 70	O Feet From The West Line
Section 36	Townshin 19S Ra	nge 24E	ARADIA Eddy ou
Section 36	Township 198 Ran	B	NMPM Eddy County
	3619.5' GR	,,,,	<i>\(\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
11. Check	k Appropriate Box to Indicate N	Nature of Notice R	eport, or Other Data
	NTENTION TO:	<u> </u>	SEQUENT REPORT OF:
		000	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB		EMENT JOB
OTHER:		OTHER: Producti	ion Csg, Perforate, Treat X
12. Describe Proposed or Completed Opwork) SEE RULE 1103.	erations (Clearly state all pertinent details, an	d give pertinent dates, inclu	ding estimated date of starting any proposed
jts 26# N-80 LT&C, LT&C, casing set 7 5504'. Cemented i 1.31, weight 15.3) sx Pacesetter Lite w/5# salt and .4% 10 sacks first st 7489' and 7510'. Perforated 7738-77 53, 54, and 7755'.	43 jts 26# J-55 L&TC, 1 2976'. Float shoe set 79 In 2 stages. 1st stage: PD 10:30 PM 2-16-89. C w/5# salt (yield 1.98 CF-14 (yield 1.32, weigh age and 50 sacks on seco	16 jts 23# J-55 76', float coll 700 sx Class H Circulate thru , weight 12.4). t 14.8). PD 6: nd stage. WOC. t DV tool at 55 ollows: 7738,	39, 40, 41, 42, 43, 45, 48, 52,
,	true and complete to the best of my knowledge and		
SKONATURE (Vanida)	Doodles m	Production Su	
TYPEORPRINT NAME Juani	ita Goodlett		тецерноме мо. 505/748—1
(This space for State Use) Original	ginal Signed By Aike Williams		FEB 2 8 1983
APPROVED BY		JE	DATE