

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different interval. Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

Oil ☒ Gas ☐ Other ☐

Name of Operator
Siete Oil & Gas Corporation

AUG 15 '88

Address of Operator

P.O. Box 2523

Roswell, NM 88202-2523

O. C. D.

ARTESIA, OFFICE

Location of Well (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface 1980' FSL & 1980' FEL, NW $\frac{1}{4}$ SE $\frac{1}{4}$, Unit Letter J

1. IF DRILLING, ALLOTTED TO DATE DATE

2. DATE OF REPORT DATE

3. NAME OF LAND OWNER

Osage Federal

4. WELL NO.

1

5. NAME AND LOCATION OF WELLCAT
UND. PARKWAY DELAWARE
Wildcat

6. SEC. T. R. N. OR S.E. AND QUARTER OR AREA

Sec. 35: T19S, R29E

7. COUNTY OR PARISH

Eddy

8. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

WELL OR ALTER CASING

MULTIPLE COMPLETS

ABANDON

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

Intermediate Casing

REPAIRING WELL

ALTERING CASING

ABANDONMENT

X

(Note: Report results of multiple completions on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give submerline latitudes and measured and true vertical depths for all markers and space parts used in this work.)

7/26/88

Reached intermediate casing depth 3201' on 7/24/88 @ 2:30 AM GIH w/12 jts. 32# & 64 jts. 24# 8 5/8" J-55 csg, set @ 3193', cement w/1540 sks (POZ-A & HEII), did not circulate cement, TOC @ 2300' by temp survey, begin 1" operation as follows:

- (1) Set 50 sx plug - tag @ 1710'
- (2) Set 100 sx plug - tag @ 1617'
- (3) Set 100 sx plug - tag @ 1270'
- (4) Set 150 sx plug - tag @ 1030'
- (5) Set 400 sx plug - tag @ 836'
- (6) Set 200 sx plug - tag @ 744'
- (7) Set 320 sx plug - circ 55 sx to surface

Resume drlg @ 4:00 AM on 7/26/88

RECEIVED
Aug 3 10 53 AM '88

18. I hereby certify that the foregoing is true and correct

SIGNED H. D. Justice

TITLE V.P. Drilling/Production

DATE 8/2/88

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

SJS

*See Instructions on Reverse Side