

BUREAU OF LAND MANAGEMENT

LC-029387-D

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation.
See APPLICATION FOR PERMIT-- for such proposals.)

Oil Well ☒ Gas Well ☐ Other ☐

Name of Operator
Siete Oil & Gas Corporation

RECEIVED

Address of Operator

P.O. Box 2523

Roswell, NM 88202-2523

Location of Well (Report location clearly and in accordance with any State requirements.
(See also space 11 below.)
At surface

900' FSL & 660' FWL, Unit Letter M, SW $\frac{1}{4}$ SW $\frac{1}{4}$

O. C. D.

ARTESIA, OFFICE

Phone No

30-015-25966

Elevations (Show whether of, to, or from)

3561' GR

1. If needed, attached to this form

2. Date of Report

3. Date on which Report
Pueblo Federal

4. Well No.

1

5. Name and No. of Wellcat

Wildcat *BONE SPRING*6. Sec., T., R., or S. and
Quarter on Map

Sec. 30: T18S, R31E

7. County on Map

Eddy

8. State

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

REPAIR WELL

(Other)

FULL OR ALTER CASING

MULTIPLE COMPLETES

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completions on Well
Completion or Abandonment Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give azimuthal headings and measured and true vertical depths for all markers and open parts (omit to this work).)

9/24/88 TOH w/tbg, MIRU Schlumberger, perforate Garyburg as follows: 3709', 3710.5', 3725', 3726.5', 3728', 3729.5', 3731', 3732.5', 3734', 3735', 3736.5', 3754', 3755', 3757', 3759', 3760.5', 3762', 3763', 3764.5', 3766' & 3767' w/1 JSPF (total 21 perforations), GIH w/CIBP & tbg, set CIBP @ 4800', spot 2 $\frac{1}{2}$ bbls acid across perfs, POOH, GIH w/treating pkr & tbg, set pkr @ 3600', acidize Grayburg interval 3709'-3767' w/1250 gal 15% HCL, breakdown @ 2600, AIR-3 BPM, AIP-2400, ballout to 3000 PSI, FPIP-1400, ISIP-1100, @ 15 min-810, start swabbing.

9/25/88 Recovered 56 BF, no shows, FL @ 2000'. SION.

RECEIVED

CONFIDENTIAL

18. I hereby certify that the foregoing is true and correct

SIGNED *Cathy Batley*

TITLE Drilling/Production Secretary DATE 9/30/88

(This space for Federal or State other use)

ACCEPTED FOR RECORD

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

OCT 17 1988

SJS

*See Instructions on Reverse Side CARLSBAD, NEW MEXICO