

BUREAU OF LAND MANAGEMENT

LC-029387-D

01/51

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
See "APPLICATION FOR PERMIT" for such proposals.)WELL ☒ GAS ☐ OTHER ☐

NAME OF OPERATOR

Siete Oil & Gas Corporation

ADDRESS OF OPERATOR

P.O. Box 2523

Roswell, NM 88202-2523

RECEIVED

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 33 below.)930' FSL & 660' FWL, Unit Letter M, SW $\frac{1}{4}$ SW $\frac{1}{4}$

JUL 19 '89

O. C. D.

ARTESIA, OFFICE

PHONE NO

30-015-25966

ELEVATIONS (Show whether OF, TO, OR ON)

3561' GR

1. DATE OF NOTICE, REPORT, OR OTHER DATA

2. DATE OF NOTICE, REPORT, OR OTHER DATA

3. NAME OF LEASED LAND

Pueblo Federal

4. WELL NO.

1

5. NAME AND LOCATION OF WILDCAT

Wildcat *Boys Spring*6. SEC. T. R. S. OF LAND AND
COUNTY OR AREA

Sec. 30: T18S, R31E

7. COUNTY OR PARISH

Eddy

8. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER DEPTH-OUT

FRACTURE TEST

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

WELL OR ALTER CASING

MULTIPLE COMPLETES

ABANDON*

CHANGE PLANS

COMPLETION REPORT OF:

WATER DEPTH-OUT

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completions on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

33. DESCRIBE PROPOSED OR COMPLETED OPERATION (Clearly state all pertinent details and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface bearings and measured and true vertical depths for all markers and open parts from to this work.)

10/24/88 TOH w/tbg & pkr, SION.

10/25/88 RU Schlumberger & perfed interval 3543'-3563' w/13 perforations, TIH w/pkr & RBP, set RBP @ 3615', test to 2000#, held ok, spot 1 bbl acid across perfs, set pkr @ 3510', formation broke @ 2300 PSI, acidize w/1000 gal 15% HCl, divert w/26 ballsealers, AIR-2.45 BPM, AIP-1900, max-4050, balled out to 4050, surge balls, FPIP-1940, ISIP-1670, @ 5 min-1630, @ 10 min-1630, @ 15 min-1620, begin swabbing from SN. ..

NOV 4 11 33 AM '88
OCEANOGRAPHIC
AREAS

RECEIVED

34. I hereby certify that the foregoing is true and correct

SIGNED

*Cathy Batley*TITLE Drilling/Production Secretary DATE 10/27/88

(This space for Federal or State official use)

ACCOMPLISHED FOR RECORD

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 8 1988

SJS

*See Instructions on Reverse Side