

SUNDRY NOTICE AND REPORTS ON WELLS

File out on the form for proposals to drill or to deepen or plug back or to abandon well.

APPLICATION FOR PERMIT TO DRILL OR TO DEEPEN OR TO PLUG BACK OR TO ABANDON WELL

RECEIVED

NAME OF OPERATOR

Siete Oil & Gas Corporation

JAN 3 11 50 AM '89

ADDRESS OF OPERATOR

P.O. Box 2523

Roswell, NM 88202-2523

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

660' FSL & 1980' FWL, SE $\frac{1}{4}$ SW $\frac{1}{4}$, Unit Letter N

RECEIVED

WELL NUMBER

30-015-20028

WELL DEPTH (Show whether in ft. or in m.)

3316' GR

FEB 16 '90

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENT TO:

TEST WATER DEPTH

☐
☐
☐
☐

WELL OR ALTER CASING

MULTIPLE COMPLETES

ABANDON

CHANGE PLANE

☐
☐
☐
☐
☐
☐

COMPLETION REPORT ON:

WATER DEPTH

☐
☒
☒
☐

PRODUCTION TREATMENT

ABANDONING OR ABANDONING

(Other)

Int. Csg, TD, Prod Csg

DETAILED WELL

ABANDONING CASING

ABANDONMENT

☐
☐
☐
☒

(Note: Report results of multiple completions on Well Completion or Recombination Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATION (Clearly state all pertinent details, and give pertinent data including estimated date of starting any proposed work. If well is directionally drilled, give substantial latitudes and measured and true vertical depths for all markers and given parts down to this work.)

- 12/9/88 TD 12 $\frac{1}{4}$ " hole to 3200' @ 12:30 PM, RU & ran 75 jts (3226') 8 5/8" 24# J-55 csg, set @ 3200' w/100 sks 35/65 POZ + additives, 500 sks 35/65 POZ + additives, tail-in w/200 sks class C neat + additives, PD @ 9:00 PM, 1" cement to surface.
- 12/14/88 TD 7 7/8" hole to 5000' @ 1:30 PM, RU Schlumberger & ran CNL/LDT, DLL/MSFL & EPT, logger's TD @ 5000'.
- 12/15/88 RU & ran 120 jts (5004') 5 $\frac{1}{2}$ " 15.5# J-55 csg, set @ 5000' w/420 sks tail-in Std + additives, PD @ 11:30 PM, released rig @ 1:00 PM.
- 12/16/88 RU Schlumberger & ran CBL on interval 2700'-4942', logger's TD @ 4948', perfed Delaware inter 4187'-4217' w/21 perforations, TIH w/SN & 2 3/8" tbg.
- 12/17/88 Spot 1 bbl acid over perfs, set SN @ 4157', formation broke @ 2655, acidized w/1000 gal 15% HCl + 42 ballsealers, AIR 3 BPM, AIP-1700, max-292 (balled out), FPIP-1485, ISIP-1080, fraced w/18,000 gal 30# XL, 2000# 100 mesh, 28,160# 20/40 & 16,260# 12/20, AIR-7 BPM, AIP-1900, max-3100, FPIP-1900, ISIP-1080, @ 5 min-1035, @ 10 min-1017, @ 15 min-1003, TIH w/tbg to 4157', reset SN @ 4157', SION, begin swabbing tomorrow.

18. I hereby certify that the foregoing is true and correct

SIGNED Cathy C. Batley

TITLE Drilling & Production Secretary DATE 12/27/88

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY _____

TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 9 1989

SUNDRY NOTICES AND REPORTS ON WELLS

COMMISSION

(Do not use this form for proposals to drill or to deepen or plug existing oil or gas wells. Use APPLICATION FOR PERMIT-- on and after 8/1/88)

82810

Oil ☒ Gas ☐ Other ☐

NAME OF OPERATOR

Siete Oil & Gas Corporation

RECEIVED

ADDRESS OF OPERATOR

P.O. Box 2523

Roswell, NM 88202-2523

DEC 16 '88

LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 33 below.)

At surface

660' FSL & 1980' FWL, SE $\frac{1}{4}$ SW $\frac{1}{4}$, Unit Letter N

O. C. D.

ARIZONA, OFFICE

1. DATE OF REPORT DATE

2. NAME OF LAND OWNER

Osage Federal

3. WELL NO.

4

4. NAME AND FULL OR VULGAR

Parkway Delaware

5. SEC. T. R. N. ON MAP AND QUAD ON AREA

Sec. 35: T19S, R29E

6. PHONE NO

30-015-26028

7. ELEVATIONS (Show whether of, to, or on)

3316' GR

8. COUNTY ON MAP

Eddy

9. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

REPAIR WELL

(Other)

FILL OR ALTER CASING

MULTIPLE COMPLETES

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Spud, Surface Csg, Logging

(Note: Report results of multiple completes on Well Completion or Description Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

10. DESCRIBE PROPOSED OR COMPLETED OPERATION (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12/1/88 LaRue Rig #2 spudded 17 $\frac{1}{2}$ " hole @ 1:00 PM.

12/2/88 TD 17 $\frac{1}{2}$ " hole to 360' @ 3:00 AM, RU & ran 9 jts (381') 13 3/8" 48# J-55 csg, set @ 381', cemented w/200 sks 35/65 POZ w/6% D-20, 3% CaCl, $\frac{1}{4}$ # D-29, tail-in w/200 sks HEII w/3% CaCl, $\frac{1}{4}$ # D-29, PD @ 8:30 PM, circ 65 sks to pit, WOC.

12/6/88 TD 12 $\frac{1}{4}$ " hole to 1700' @ 5:15 AM, RU Schlumberger, ran LDT/CNL & DLL/MSFL on interval 0'-1687', logger's TD @ 1690', finished logging @ 11:30 AM, resume drilling.

ACCEPTED FOR RECORD

DEC 14 1988

CARLSBAD, NEW MEXICO

RECEIVED
DEC 12 9 07 AM '88
CARLSBAD AREA
OFFICE

11. I hereby certify that the foregoing is true and correct

SIGNED Cathy BotleyTITLE Drilling/Production SecretaryDATE 12/9/88

(This space for Federal or State use only)

APPROVED BY _____

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: