

+clsr
dp

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAR 24 1993

O.C.D.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		WELL API NO. 30-015-26047
2. Name of Operator YATES PETROLEUM CORPORATION		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator 105 South 4th St., Artesia, NM 88210		6. State Oil & Gas Lease No. V-1116
4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>2230</u> Feet From The <u>East</u> Line Section <u>2</u> Township <u>20S</u> Range <u>24E</u> NMPM <u>Eddy</u> County		7. Lease Name or Unit Agreement Name Cacti AGB State Com
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3640.1' GR		8. Well No. 1
		9. Pool name or Wildcat Und. Cemetary Morrow

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: Abandon perfs in Cemetary Morrow and recomplete in Canyon <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to abandon perforations 9128-9137' and 9173-9183' (Cemetary Morrow) and perforate Canyon Dolomite 7699-7810' and stimulate as follows:

- TOOH w/tubing and packer. TIH w/CIBP and set at 9050'. Place 35' of cement on top of CIBP.
- GIH w/4" casing gun and perforate Canyon Dolomite with 38 .50" holes (180 degree phasing as follows: 7699, 7701, 04, 07, 09 (2 SPF, 10 holes); 7753, 54, 54, 66, 68, 74, 76, 80, 82 & 7786' (2 SPF, 20 holes) and 7804, 06, 08 & 7810' (2 SPF, 8 holes).
- TIH w/tubing, packer & RBP.
- Straddle and acidize as follows: 7804-7810' w/5000 gallons 20% HCL & ball sealers; 7753-7786' w/12000 gallons 20% HCL and ball sealers and 7699-7709' w/3000 gallons 20% HCL and ball sealers.
- Straddle entire interval and swab back load.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE March 23, 1993
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE MAR 31 1993

CONDITIONS OF APPROVAL, IF ANY: