

Submit 3 Copies  
to Appropriate  
District Office

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico  
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

Santa Fe	
Le	
SLM	
Land Office	
B of M	
Operator	

Form C-103  
Revised 1-1-89

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	WELL API NO. 30-015-26062
2. Name of Operator YATES PETROLEUM CORPORATION	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator 105 South 4th St., Artesia, NM 88210	6. State Oil & Gas Lease No. VB-298
4. Well Location Unit Letter 0 : 660 Feet From The South Line and 2310 Feet From The East Line Section 20 Township 19S Range 23E NMPM Eddy County	7. Lease Name or Unit Agreement Name Foothills AGH State
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4046.4' GR	8. Well No. 1
	9. Pool name or Wildcat Wildcat MORROW

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate, Treat, Test Well <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-18-89 - 5-4-89. Swabbed and tested well.

5-4-89. Set CIBP at 8050' and capped w/35' cement. Perforated 6741-50' w/10 - .41" holes (1 SPF). Acidized perfs 6741-50' w/2000 gals 15% NEFE acid.

5-9-89. Perforated 6662-66' and 6676-80' w/10 .41" holes. Acidized perfs 6662-66', 6676-80' w/2000 gals acid.

5-12-89. Set CIBP at 6600' and capped w/35' cement. Perforated 5811-16' w/10 .42" holes (2 SPF). Acidized perfs 5811-16' w/1000 gals 7 1/2% Spearhead acid w/2% HF acid + ball sealers. No shows.

5-16-89. Set CIBP 5750' and capped w/35' cement. Perforated 4628-4739' w/28 .45" holes as follows: 4628, 29, 30, 31, 32, 33, 41, 4690, 91, 92, 93, 95, 4705, 06, 07, 17, 19, 20, 21, 22, 27, 31, 32, 35, 36, 37, 38 and 4739'. Acidized perforations 4628-4739' with 8000 gals 15% NEFE acid, 35 ball sealers and 160# Block in 6 stages.

5-19-89. Swabbed well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 6-7-89  
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS

APPROVED BY SUPERVISOR, DISTRICT II TITLE SUPERVISOR DATE JUN 12 1989

CONDITIONS OF APPROVAL, IF ANY: