

45r
+ DP

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SEP 26 '89

O. C. D.

WELL API NO.
30-015-26138

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line

Section 22 Township 20S Range 24E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3663' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐ CASING TEST AND CEMENT JOB ☐
OTHER: ☐ OTHER: Perforate, Treat ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-8-89. TD 9500'. Drilled out DV tool. Perforated 9135-42' w/16 .42" Holes. Dropped bar on knockout disk. Had gas to surface in 5 minutes. Well flowed 20 minutes and died. Swab with show of gas. Set cement retainer at 9110'. Squeezed perms 9135-42' w/100 sx C1 H. Perforated 9079-81' and 9089-91' w/8 .42" holes (1 SPF). Acidized perms w/750 gals 15% Morrow acid. Swabbed with show of gas.

9-16-89. Set CIBP at 9055'. Perforated 8791-8814' w/10 .42" holes. Acidized perms w/1500 gals 7½ MS acid + N2 and ball sealers. Swabbed well dry.

9-20-89. Set CIBP at 8750' w/35' cement cap. Perforated 8163-77' w/12 .42" holes. Acidized perms w/1500 gals 15% NEFE acid, N2 + ball sealers. Well flowed acid gas.

9-22-89. Set CIBP at 8135' w/35' cement cap. Perforated 7609-7716' w/20 .42" holes as follows: 7609, 11, 13, 15, 17, 25, 27, 30, 36, 41½, 55, 58, 60, 62, 64, 66, 68, 83, 7709 and 7716'.

Straddled perms 7609-7716' (20 holes) and acidized w/6000 gals 20% NEFE acid.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 9-25-89

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY

MIKE WILLIAMS

SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE SEP 26 1989

CONDITIONS OF APPROVAL, IF ANY: