

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JAN 3 1994

WELL API NO.	30-015-26209
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-1576
7. Lease Name or Unit Agreement Name	Parkway 36 State
8. Well No.	9
9. Pool name or Wildcat	Parkway (Delaware)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3326.6' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry Hole	2. Name of Operator Santa Fe Energy Operating Partners, L.P.
3. Address of Operator 550 W. Texas, Suite 1330, Midland, Texas 79701	4. Well Location Unit Letter I : 1980 Feet From The South Line and 330 Feet From The East Line Section 36 Township 19S Range 29E NMPM Eddy County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>
SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Attached is a revised plugging procedure for your approval. Due to errors in the originally submitted Notice of Intent to plug and abandon, I respectfully re-submit this revised Notice of Intent.

Notify N.M.O.C.C. in sufficient time to witness

Plugging

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry McCullough TITLE Sr. Production Clerk DATE Dec. 30, 1993
TYPE OR PRINT NAME Terry McCullough TELEPHONE NO. 915/687-3551

(This space for State Use)

APPROVED BY [Signature] TITLE EDD DATE 1/2/94
CONDITIONS OF APPROVAL, IF ANY:

Plugging and Abandonment
Parkway 36 State No. 9

Procedure:

1. Notify state OCD 24 hours in advance of operations.
2. RUPU. RUWL. Run guage ring/junk basket to 3710'. Set CIBP @ 3700' by wireline.
3. PU and RIH with 2 3/8" OE tubing to 3700'. Circulate hole with 9.5 ppg mud. Spot Class C cement plugs as follows:

<u>Depth to EOT</u>	<u>Sacks</u>	<u>Height</u>	<u>Purpose</u>
3700'	40	590'	On top of CIBP, Span Delaware top and 7" shoe.
1433'	15	220'	Cover Yates top and Span 10 3/4" shoe.

4. POH with tubing. Cut off 4 1/2" casing at approx 1000' and pull same. Cut off 7" casing at approx 500' and pull same. RIH with OE tubing and spot Class C plugs as follows:

<u>Depth to EOT</u>	<u>Sacks</u>	<u>Height</u>	<u>Purpose</u>
50' inside of 4 1/2" stub	15	117'	Cover 4 1/2" stub
50' inside of 7" stub	85	230'	Cover 7" stub and 16" casing shoe
50'	20	50'	Surface plug

5. Cut off wellhead 3' below ground level and install 4"x4" dry hole marker containing the following information:

Santa Fe Energy Operating Partners, LP
Parkway 36 State No. 9
1980 FSL & 330' FEL
I-36-19S-29E, NMPM
Eddy County, New Mexico

6. Clean location and remove any surplus equipment.