

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JAN 25 1994

WELL API NO.	30-015-26209
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-1576
7. Lease Name or Unit Agreement Name:- Parkway 36 State	
8. Well No.	9
9. Pool name or Wildcat	Parkway (Delaware)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3326.6' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole

2. Name of Operator
Santa Fe Energy Operating Partners, L.P.

3. Address of Operator
550 W. Texas, Suite 1330, Midland, Texas 79701

4. Well Location
Unit Letter I : 1980 Feet From The South Line and 330 Feet From The East Line
Section 36 Township 19S Range 29E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1/17/94: Notified ODC that plugging operations were about to begin.
- 1/19/94: RUPU. RIH w/ gauge ring and junk basket to 3710'. Set CIBP by wireline at 3700'. Ran tubing to 3700'. Circ'd w/ 9.5 ppg mud. SDFN.
- 1/20/94: Broke circ. Spot 40 sx C1 C cmt on top of CIBP at 3700'. POH w/ 71 jts 2-3/8" tbg. EOT at 1456'. Pump 25 sx C1 C cmt (14.8 ppg). POH w/ tubing. Cut csg off at 1025'. POH w/ 24 jts 4-1/2" casing and 4-1/2" x 6' stub cut off. Weld 7" pick up jt on 7" casing. SWI. SDFN.
- 1/21/94: Free point 7". Shot casing off at 600'. POH w/ 14 jts 7" 20# J-55 csg, 2 short jts, 7" cut off stubs. NU BOP. RIH w/ 33 jts tbg. Spot 25 sx C1 C cmt at 1043'. POH w/ tbg. Load csg w/ 5 BW, no loss of fluid. State allowed us not to tag plug from 1043'. RIH to 650'. Spot 50 sx C1 C cmt. POH w/ tbg. EOT at 50'. Spot 20 sx C1 C cmt. SWI and SDFN.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry McCullough TITLE Sr. Production Clerk DATE 1/24/94
TYPE OR PRINT NAME Terry McCullough TELEPHONE NO. 915/687-3551

(This space for State Use)

APPROVED BY [Signature] TITLE SDO Rep DATE 2/9/94
CONDITIONS OF APPROVAL, IF ANY:

1/22/94: Installed dry hole marker. Cut off deadmen and cleaned location.
Well plugged and abandoned on 1/21/94.