

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instruct on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	RECEIVED	5. LEASE DESIGNATION AND SERIAL NO. LC 029393-B 215F
2. NAME OF OPERATOR TEXACO INC.	FEB - 1 '90	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. BOX 3109 MIDLAND, TEXAS 79702	ARTESIA, OFFICE	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirement. See also space 17 below.) At surface 330' FNL + 1980' FEL		8. FARM OR LEASE NAME KINCAID-WATSON FEDERAL
14. DEWANE NO. API 30-015-26225	15. ELEVATIONS (Show whether DF, RT, GR, etc.) GR 3632, KB-3650	9. WELL NO. 1
		10. FIELD AND POOL, OR WILDCAT SHUGART BONE SPRING, NORTH
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SEC. 18, T-18-S, R-31-E
		12. COUNTY OR PARISH EDDY
		13. STATE NM

18.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) UNSET RBP AT 8850'. SET RBP AT 8350' AND TEST TO 4000 # OK.
- 2) ATLAS PERF SECOND BOWE SPRINGS SAND WITH 2JSPP: 8198-8204, 8218-20, 8222-30, 8264-68, 8304-06
- 3) WESTERN ACIDIZED WITH 2500 GAL 7 1/2% NEFE WITH 66 BALLS. Job COMPLETE AT 11:15 AM 1-15-90
- 4) WESTERN FRAC WITH 19000 GAL 2% GELLED XL KCL + 37500 # 20/40 SAND + 12,500 # RESIN COATED SAND. Job COMPLETE AT 2:30 P.M. 1-16-90
- 5) TESTING SWAB 10 Hours. REC. 4 BNO + 40 BLW 1-19-90
- 6) SET RBP @ 8110'. Test to 4000#, 30 min, OK. SHOT 2 SACKS SAND ON RBP.
- 7) ATLAS PERF WITH 2JSPP - 7900 - 7904, 7912-7945 (74 Holes)
- 8) WESTERN ACIDIZE WITH 3000 GAL. 15% NEFE WITH 100 BALLS. Job COMPLETE AT 8:15 A.M. 1-24-90.
- 9) 1-24-90. SWAB 8 hours. REC. 22 BNO + 108 BLW
- 10) TESTING.

18. I hereby certify that the foregoing is true and correct

SIGNED

Carl Barker

TITLE

Drilling Superintendent

DATE

1-25-90

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

Ad

JAN 29 1990

*See Instructions on Reverse Side

CARLSBAD, NEW MEXICO