NM 29228

CIST

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	PURCM	i apyk	OAFD	
Be	idget Bur	esu No.	1004-0	113
	Expires:			
1	Destaura	1 4	A1-1 1	٠.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

6. If Indian, Allottee or Tribe Name

SUBMIT	7. If Unit or CA, Agreement Designation	
1. Type of Well X Well Gas Other		A MUNICIPAL AND
Well	8. Well Name and No. BENSON 3 FEDERAL # 3	
MERIDIAN OIL INC. ;/	9. API Well No.	
3. Address and Telephone No.		
P.O. Box 51810 Midland, TX 79710	10. Field and Pool, or Exploratory Area SHUGART (QUEEN)	
 Location of Well (Footage, Sec., T., R., M., or Survey De. H, 1650' FNL & 330' FEL 		
SEC. 3, T19S, R30E		11. County or Parish, State EDDY CO.
2. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REP	ORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTI		ON
X Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Recompletion Plugging Back Casing Repair	New Construction Non-Routine Fracturing Water Shop-Off

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Altering Casing

Other PARAFFIN SOAK, ACIDIZE

& SCALE SQUEEZE

1. MIRUSU. PULL RODS AND PMP. INSTALL BOP

Final Abandonment Notice

- 2. POOH W/2 7/8" TBG, PICKUP RETRIEVABLE BRIDGE PLUG AND PACKER FOR 5 1/2" 15.5# CASING AND TRIP BACK IN HOLE TO +/-3100'. SET RBP AT +/-3100' AND RETRIEVABLE PACKER AT 3050'
- 3. MIX ONE DRUM OF PARAFFIN/ASPHALTENE TREATMENT AND ONE DRUM PARAFFIN DISPERSANT AND PMP DOWN 2 7/8" TBG. FLUSH W/18 BBLS LEASE CRUDE. SHUT IN
- 4. SWAB BACK LOAD VOLUME
- 5. RIG UP ACID ENGR. AND TREAT THE UPPER PENROSE PERFS (3080'-3086').
- 6. RD ACID ENGR. AND RU SWAB, SWAB BACK ACID RESIDUE AND LOAD.
- 7. MIX TWO DRUMS OF SCALE INHIBITOR IN 13 BBLS 2% KCL WATER AND PMP DOWN TBG. FLUSH W/35 BBLS OF 2% KCL.
- 8. RELEASE PACKER, LOWER TUBING AND RETRIEVE RBP. RESET RBP AT +\-3050' AND PACKER AT 2900'
- 9. MIX THREE DRUMS OF PARAFFIN/ASPHALTENE TREATMENT AND THREE DRUMS OF PARAFFIN DISPERSANT AND PMP DOWN 2 7/8" TBG. FLUSH W/18 BBLS LEASE CRUDE. SHUT IN
- 10. SWAB BACK LOAD VOLUME
- 11. RU ACID ENGR. AND TREAT QUEEN PERFS (2958'-2991').
- 12. RD ACID ENGR. AND RU SWAB. SWAB BACK ACID RESIDUE AND LOAD.
- 13. MIX TWO DRUMS OF SCALE INHIBITOR IN 13 BBLS OF 2% KCL WATER AND PMP DOWN TBG. FLUSH W/100 BBLS OF 2% KCL.
- 14. RELEASE PACKER, RETRIEVE RBP AND POOH.

4. I hereby tertify that the foregoing is true and correct Signed CONNA WILLIAMS	Title PRODUCTION ASSISTANT	Det: 10/26/93
(This space for Federal or State office use) Approved by	Title	Date
Conditions of approval, if any:	J Jasa 2 4 1993	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction.