

BUREAU LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		RECEIVED	
2. NAME OF OPERATOR Siete Oil and Gas Corporation ✓		APR 30 '90	
3. ADDRESS OF OPERATOR P.O. Box 2523 Roswell, NM 88202-2523		O.C.D. ARTESIA, OFFICE	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2310' FSL & 1750' FEL, NW $\frac{1}{4}$ SE $\frac{1}{4}$, Unit Letter J		5. LEASE DESIGNATION AND SERIAL NM-24160	
6. PERMIT NO. 30-015-26283		7. UNIT AGREEMENT NAME	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3320' GR		8. FARM OR LEASE NAME Osage Federal	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		9. WELL NO. 16	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)		10. FIELD AND POOL OR WILDCAT Parkway Bone Spring	
18. I hereby certify that the foregoing is true and correct		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec. 34, T19S, R29E	
19. SIGNATURE Cathy Dotley-Sely		12. COUNTY OR PARISH Eddy	
20. TITLE Drig. & Prod. Tech.		13. STATE NM	

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

3/23/90 DO DV Tool @ 6035', Trip to 8300', circ hole clean w/2% KCl, lay dn drl assembly, SION.

3/24/90 RU Schlumberger, ran CBL, tOC @ 2750', perforate 7002'-7072' w/15 perfs, TIH w/pkr & tbg to 7072', spot 2 bbls acid.

3/25/90 RU Dowell Schlumberger & acidized w/2000 gal 15% HCl + 30 ballsealers, set pkr @ 6905', AIR-5 BPM @ 1700 PSI, max-4120, FPIP-1730, ISIP-950, @ 5 min-880, @ 10 min-860, @ 15 min-840, fraced w/71,000 gal 25# XL, 166,000# 16/30 & 28,000# RCS 16/30, AIR-30 BPM @ 1000 PSI, max-1830, FPIP-1680, ISIP-1010, @ 5 min-860, @ 10 min-825, @ 15 min-800, begin flowback.

3/26/90 This morning FL 600' FS, rec. 340 bbls load, swabbing w/trace oil and good gas.

ACCEPTED FOR RECORD

APR 26 1990

CARLSBAD, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Drig. & Prod. Tech.

DATE 4/11/90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side