

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAY 10 1990

O. C. D.

WELL API NO. 30-015-26303
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-2781
7. Lease Name or Unit Agreement Name Huisache AHI State Com
8. Well No. 1
9. Pool name or Wildcat Und. Morrow
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3624' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter H : 1980 Feet From The North Line and 660 Feet From The East Line
Section 2 Township 20S Range 24E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Production Casing set <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 9441'. Reached TD 5-4-90. Ran 224 jts 7" casing as follows: 46 jts 26# N-80 LT&C, 20 jts 26# J-55 LT&C, 24 jts 23# N-80 LT&C, 77 jts 23# J-55 LT&C, 54 jts 23# N-80 LT&C, and 3 jts 26# N-80 LT&C, casing set 9441'. Float shoe set 9441', float collar set 9400'. DV tool set 5303'. Marker joints set 7563'. Cemented stage I with 500 gals mud flush, 500 gals Surebond. Tailed in w/1200 sx Class H w/.8% CF-14, 10#/sx salt, 8#/sx Hiseal, (yield 1.19, wt 15.7). PD 1:30 PM 5-6-90. Bumped plug to 2850 psi, float held okay. Circulate thru DV tool 2 hrs. Circulated 70 sx. Cemented stage II with 975 sx Pacesetter Lite C .4% CF-14, 5#/salt and 8# Hyseal (yield 1.98, wt 12.4). Tailed in w/ 100 sx Class H (yield 1.18, wt 15.6). PD 5:00 PM 5-6-90. Bumped plug to 2900 psi, OK. DV tool closed and held okay. Circulated 80 sx. WOC 18 hrs. Rig released 9:00 PM 5-6-90.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 5-7-90
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 16 1990