## Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Manierals and Natural Resources Department

Form	C	-10	3
Revis	ed	1-1	-8

DISTRICT I	OIL CONSERVATION DIVISION
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088

SUPERVISOR, DISTRICT IS

CONDITIONS OF AFTROVAL, IF ANY

P.O. Box 2088

Santa Fe, New Mexico 87504820881V5D

WELL API NO. 30-015-26303

Santa Fe, New Mexico 87504RZBBHV&D					
P.O. Drawer DD, Artesia, NM 882	210	Wich also demonstate and	5. Indicate Type of Lease STATE XX FEE		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM	87410	JUN 13'90	6. State Oil & Gas Lease No. E-2781		
0.11.10.00	AND DECORTS OF				
( DO NOT USE THIS FORM FO	NOTICES AND REFORTS ON OR PROPOSALS TO DRILL OR TO DE RESERVOIR. USE "APPLICATION FO FORM C-101) FOR SUCH PROPOSALS	OR PERMIT	7. Lease Name or Unit Agreement Name		
1. Type of Well:	_	<u> </u>	Huisache AHI State Com		
WEIT XX ME	ELL OTHER				
2. Name of Operator YATES PETROLEUM CO	ORPORATION	$\checkmark$	8. Well No.		
3. Address of Operator			9. Pool name or Wildcat		
105 South 4th St.	, Artesia, NM 88210		North Dagger Draw Upper Penn		
4 Well Location			Fact		
Unit Letter H:	1980 Feet From The North	Line and ODU	Feet From The East Line		
2	Township 20S		NMPM Eddy County		
Section 2	10. Elevation (Show	whether DF, RKB, RT, GR, etc.)			
	//////////////////////////////////////	4' GR	<u> </u>		
11. C	Check Appropriate Box to Ind	icate Nature of Notice, R	Report, or Other Data		
	OF INTENTION TO:	SUE	SSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB		
	لســـا	OTHER: Perfor	(Fig. 1)		
OTHER:					
WAREL CEE BITTE 1103			uding estimated date of starting any proposed		
6-1-90. Perfor 7677, 79, 81, 8	ated Upper Canyon /659- 3,85, 7726, 28, 30, 31,	7756, 58, 60, and	acid thru perfs 7790-7814' oles as follows: 7659, 61, 63, 7762'. Acidized perforations		
6-2-90. Aciidz	e 7659-7762' via tubing	g and annulus w/1000	0 gals 20% NEFE acid in 2 stages		
$\overline{w/1000}$ # block.	Swabbed well.				
6-3-90. Return	well to production.		•		
Perforations on	oen: 7659-7762'; 7790-7	7814 <b>'</b>			
101101a020119 of					
I have easify that the information	above is true and complete to the best of my kno	wledge and belief.			
Thatby cally the the internation	Doudlitt	Production S	Supervisor pare 6-12-90		
SIGNATURE	- Call	mu:			
TYPE OR PRINT NAME	Juanita Goodlett		<u>теценноме но. 505/748-1</u> 47.		
(This space for State Use)	ORIGINAL SIGNED BY				
(Tittle share for person cac)	MIKE WILLIAMS		DATE JUN 1 5 1990		
	SUPERVISOR, DISTRICT IT	TITLE	DATE JUN 1 3 1880		