

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JUN 13 '90

| |
|---|
| WELL API NO. 30-015-26305 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. B-9739-19 |
| 7. Lease Name or Unit Agreement Name SAND DUNE STATE |
| 8. Well No. 2 |
| 9. Pool name or Wildcat TURKEY TRACK SR-Q-G-SA |

| | |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER | |
| 2. Name of Operator MYCO INDUSTRIES, INC. | |
| 3. Address of Operator 207 SOUTH 4th. ARTESIA, NM. 88210 | |
| 4. Well Location Unit Letter I : 1980 Feet From The SOUTH Line and 660 Feet From The EAST Line Section 11 Township 19s Range 29e NMPM EDDY County | |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3364.2 GR. | |

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PERFORATED QUEEN @ 2348, 54, 58, 59, 71, 72, 73, 75, 77, 79 & 81' ACIDIZE W/ 1200 GALS 15 % NEFE
SWAB DRY NO SHOWS. PERFORATED SEVEN RIVERS @ 1748, 52, 54, 56, 58, 71, 72 & 73' ACIDIZED W/
1000 GALS 15% NEFE SWAB DRY NO SHOWS
PROPOSE TO PLUG AND ABANDON AS FOLLOWS-
LOAD HOLE WITH MUD LADEN FLUID AND SPOT A 25 SACK PLUG @ 2400', 25 SACK PLUG @ 1850'
25 SACK PLUG @ 450' AND A 10 SACK PLUG AT THE SURFACE WITH MARKER.

Notify N.M.O.C.G. in sufficient time to witness

Plugging

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W.A. Gressett TITLE CONSULTANT DATE 6/18/90
TYPE OR PRINT NAME W.A. GRESSETT TELEPHONE NO. 748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE JUN 18 1990

CONDITIONS OF APPROVAL, IF ANY: