

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210
TELEPHONE (505) 748-1471

RECEIVED

JUN 28 10 52 AM '80

CARL
AREA

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

DRILL STEM TESTS

Saguaro AGS Federal Com #2, NM 043625
1980' FNL & 1980' FWL, Sec. 15-T20S-R24E
Eddy County, NM

DST #1 6864-6951' Lower Wolfcamp (87'): TIMES: 15", 45", 30", 60", 60", 180". RECOVERY: 100' drilling mud. SAMPLER: 200 cc mud and 190 psig. PRESSURES: IHP 3419, IFP 226-320, ISIP 536, 2nd FP 85-94, 2nd SIP 291, FFP 94-96, FSIP 479, FHP 3250.

DST #2 7236-7299' Cisco (63'): RECOVERY: 371' gas cut drilling mud and 1.81 bbls mud. SAMPLER: 5.6 cfg and 350 psi. PRESSURES: IHP 3581, IFP 414-517, ISIP 1334, FFP 198-273, FSIP 554, FHP 357.
NOTE: TIMES: 30", 60", 60".