

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-26316
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-689
7. Lease Name or Unit Agreement Name SST
8. Well No. #2
9. Pool name or Wildcat Palmillo Bone Springs

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Harvey E. Yates Company
3. Address of Operator P.O. Box 1933, Roswell, New Mexico 88202	4. Well Location Unit Letter <u>B</u> : <u>660</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>6</u> Township <u>19S</u> Range <u>29E</u> NMPM <u>Eddy</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3396.5 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Completion</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/22/90 MI & perforate 7856-86 (1 spf); Acdz w/3200 gals 20% NE-FE & BS; Swab test
5/24/90 Set CIBP @ 7840, Perf Barrier perfs @ 7782 & 7515 (2 shots each)
5/25 to 6/2/90 Squeeze 7782 w/1000 sks "H"; Squeeze 7518 w/2000 sks "H"; WOC
6/5/90 Drill out squeeze jobs & clean out to 7840 (PBD)
6/9/90 Perforate @ 7545-7691 (2 spf); Acdz w/5000 gals 7 1/2% SRA & BS; Swab test
6/12/90 Frac perfs 7545-7691 w/250,000 gals BS-50 & 390,000# LWP
6/15/90 Put on production

JUL 6 '90

C. C. D.
ARTESIA, OFFICE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE MM Young TITLE Drilling Superintendent DATE 7/5/90
TYPE OR PRINT NAME NM Young TELEPHONE NO. 623-6601

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS

APPROVED BY SUPERVISOR, DISTRICT II TITLE DATE JUL 27 1990

CONDITIONS OF APPROVAL, IF ANY: