Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

C ()	
Form C-103	
Revised 1-1-89	
Revised 11.03	

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088 CENTED
Santa Fe New Mexico 87504-2088

CONDITIONS OF APPROVAL, IF ANY

WELL API NO. 30-015-26342

DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa re, New Mexico	67304-2000	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	ı	AUG 31 '90	6. State Oil & Gas Lease No.
ar in pour locations	AND DEDODTS ON WEL	IS 3.	
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIF	AND REPORTS ON WEL BALS TO DRILL OR TO DEEPER R. USE "APPLICATION FOR PEI FOR SUCH PROPOSALS.)	OH FEDGI BHOK 10 N	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL XX WELL	OTHER		Ceniza AGZ Com
2. Name of Operator YATES PETROLEUM CORPORATI	ON .		8. Well No.
			9. Pool name or Wildcat Penn
3. Address of Operator 105 South 4th St., Artesi	a, NM 88210		Und. No. Dagger Draw Upper
4. Well Location	Feet From The South	Line and660	Feet From The East Line
	Township 20S R	24E	NMPM Eddy County
Section 2	Township 205 R 10. Elevation (Show whether 3608'	DF, RKB, RT, GR, etc.)	NWITH THE THE THE THE THE THE THE THE THE T
<i>\(\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	////		anort or Other Data
	propriate Box to Indicate	Nature of Notice, R	SEQUENT REPORT OF:
NOTICE OF INTER	NTION TO:	506	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB L
OTHER:		OTHER:	
 Describe Proposed or Completed Operation work) SEE RULE 1103. 			
TD 8190'. Reached TD 8-2 67 jts 7" 26# J-55, 91 jt casing set 8184'. Float joints set 7556-7537'. Excello gel, 750 sx Class 3:45 AM 8-27-90. Circula	s 7" 23# J-55, 22 j shoe set 8184', *f1 Cemented in two stag s H w/.8% CF-14+5#/s ated 150 sx to surfa 00 sx Pacesetter Lit 12.4). PD 7:00 AM	ts /* 23# N-80, oat collar set ses: Stage I - : x Hiseal + 10% ce. Opened DV e w/5#/sx Salt 8-27-90. Close for 3 mins, flo	follows: 15 jts 7" 26# N-80, 4 jts 7" 26# J-55, (total 8215') 8137'. DV tool set 5425'. Marker 500 gals Surebond, 500 gals Salt (yield 1.19, wt 15.7). PD tool with 450 psi and circulated + .4% CF-14 + 5#/sx Hiseal + 1/4# d DV tool with 3500 psi. Circulated at and casing held okay.
Waiting on completion uni	t.		
I hereby certify that the information above is true a	nd complete to the best of my knowledge	and belief.	
Ju anitax)	audlett	mme Production	Supervisor DATE 8-30-90
SIGNATURE	Goodlett		TELEPHONE NO. 505/748-147
MIKE.	NAL SIGNED BY WILLIAMS		SEP 1 1 1990
APPROVED BY SUPER	RVISOR, DISTRICT II	TITLE	DAIL