

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

RECEIVED

APR 30 1991

WELL API NO. 30-015-26467
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Geniza AGZ Com
8. Well No. 3
9. Pool name or Wildcat South Dagger Draw Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A WELL IN A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471	
3. Address of Operator 105 South 4th St., Artesia, New Mexico 88210	
4. Well Location Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line Section 13 Township 20S Range 24E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3603' GR	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-19-91. Drilled out DV tool @ 5400'. Cleaned out to 9400'. Perforated 7938-7966' w/18 .50" holes (2 SPF) as follows: 7938, 40, 42, 52, 54, 56, 62, 64, 7966'. Acidized perfs w/3500 gals 20% NEFE acid. Swabbed - no shows.  
3-23-91. Set sub-pump. Pumped well 8 days - produced water only.  
4-2-91. Set retainer at 7920'. Squeezed perfs 7938-7966' w/250 sx "H" Neat. Squeezed to 2600 psi. Cleaned out cement stringers to cement at 7920'. Perforated 7786-7870' w/40 - .50" holes (2 SPF) as follows: 7786, 88, 92, 94, 96, 7808, 10, 12, 14, 16, 37, 38, 39, 52, 54, 59, 61, 66, 68 and 7870'. Acidized perfs 7786-7870' w/3000 gals 20% NEFE acid. Re-acidized perfs 7786-7870' w/12000 gals 20% NEFE acid + 800# Block.  
4-7-91. Ran sub pump. Put well on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 4-29-91  
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS  
SUPERVISOR, DISTRICT II

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE APR 30 1991

CONDITIONS OF APPROVAL, IF ANY: