

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
311 S. 1st
Artesia, NM 88210

FORM APPROVED
Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

YATES PETROLEUM CORPORATION

(505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2180' FNL & 1980' FWL of Section 23-T20S-R24E (Unit F, SENW)

5. Lease Designation and Serial No.

NM-043625

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Saguaro AGS Fed Com #5

9. API Well No.

30-015-26475

10. Field and Pool, or Exploratory Area

Undes. Wolfcamp

11. County or Parish, State

Eddy Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment Canyon
☒ Recompletion Wolfcamp
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to abandon Canyon perforations and recomple to Wolfcamp as follows:

1. Nipple up BOP. POOH with pumping equipment.
2. Set CIBP at 7520'. Load hole with 2% KCL. Pressure test CIBP and casing.
3. Perforate 6490-6494' (Wolfcamp). Acidize as necessary for production.
4. Swab test.
5. Place well into production.

14. I hereby certify that the foregoing is true and correct

Signed

Alexis C. Swoboda

Title Operations Technician

Date Feb. 23, 1998

(This space for Federal or State office use)

(ORIG. SGD.) ALEXIS C. SWOBODA

Approved by

Conditions of approval, if any:

Title

PETROLEUM ENGINEER

Date

FEB 23 1998